

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/12/2019

Submitted Date:

04/15/2019

Document Number:

682504729

FIELD INSPECTION FORMLoc ID 451812 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 202 TRAVIS STREET #402

City: HOUSTON State: TX Zip: 77002

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		kevin@d90energy.com	
Housey, Melissa		melissa.housey@state.co.us	
		dsilverman@d90energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451812	LOCATION	AC			-	Mary Jane 11-5	CI
451813	WELL	XX	02/12/2019		073-06724	MARY JANE 11-5	CI

General Comment:

This is a pre-drill, construction and stormwater inspection. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Location Construction

Location ID: 451812 CDP: _____

Comment: _____

Corrective Action: A disturbance area of 4.87 acres was mapped on 4/12/2019 with a Trimble Juno 3B GPS unit; this appears to exceed the approved Form 2A for the permitted disturbance area (2.5 acres). This is being referred to OGLA

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

SLOPE ROUGHENING

Yes

Comments: Erosion BMPs:

Operator has installed surface roughening (ripping) along perimeter of the location. At time of inspection BMP appeared to be in proper functioning condition. Surface roughening is a temporary stormwater control that needs to be used in conjunction with other BMPs. Once pad construction has been completed, BMP should be replaced, or additional BMPs will need to be installed and used in conjunction with surface roughening.

Other BMPs:

There area areas where surface roughening has been installed with the slope of the location, rather than along the contour. This is not good engineering practices and will facilitate the concentration of stormwater, increases runoff velocity and increases chance of erosion degradation. Advise additional BMPs be used in conjunction with surface roughening along slopes.

Corrective Action:

Date:

Comment:**Corrective
Action:****Date:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	451812	Type:	LOCATION	API Number: -	Status:	AC	Insp. Status:	CI	
Facility ID:	451813	Type:	WELL	API Number:	073-06724	Status:	XX	Insp. Status:	CI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____ In _____

Comment _____

Soil removal and segregation in process at time of inspection. During salvage operations, Operator was observed placing subsoil horizons upon the topsoil on the northwest end of the location. This does not comply with 1002.b(1). Topsoil is required to be salvaged from all areas of disturbance (fill slopes, berms, etc.), and/or properly separated/segregated and protected.

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ In Process _____

Comment _____

Operator appears to have tracked topsoil piles on the east and southern ends of the pad. Operator does not appear to have tracked along the contour of the slopes in accordance with good engineering practices. Additional, heavy vehicle use evident on topsoil stockpiles and compaction concerns are becoming evident.

Ensure remaining topsoil and soil stockpiles are sufficiently stabilized and BMPs are installed in accordance with good engineering practices for stabilization, and to mitigate further compaction of topsoil.

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682504730	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4795235