

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2019

Submitted Date:

05/07/2019

Document Number:

689401702

FIELD INSPECTION FORM
 Loc ID 335134 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Mike Gardner		mgardner@terraep.com	
Arauza, Steven		steven.arauza@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
464273	SPILL OR RELEASE	AC	05/03/2019		-	SPILL/RELEASE POINT	EI

General Comment:

On March 6, 2019, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Spill ID 464273. Mike Gardner and Chuck from TEP were also onsite during the inspection. Weather was sunny and temperatures about 55 degrees Fahrenheit.

Operator reported a leak coming from a small hole in base of the condensate oil storage tank (Doc# 402028230). The contents of the leaking tank were emptied and a vac-truck was dispatched to the site to recover fluids from secondary containment.

Two excavations (2'x2'x2') are located south of where the leak occurred, the excavations had oily stained sidewalls. Each of the excavations had a pool of fluid in them but no oily sheen was observed (see photos). A 1" long stick was observed plugging the pin sized leak (see photos). There is also oily stained soil located on tank cement pad beneath the leak (see photos).

Inspection included visual observation of the arroyo located ~42 feet to the west and the ground surface between the leak and the arroyo (see photos). No hydrocarbon staining or odors were detected on the ground surface or in the arroyo on inspection date.

Refer to environmental section for corrective actions.

Environmental**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: 5.6

Comment: Operator reported spill on Initial F19 on 5/1/2019 (Doc# 402028230)

Corrective Action: Operator shall submit a supplemental F19 within 10-days of the initial spill/release date in addition to a supplemental F19 with laboratory analytical upon receipt from the lab at that time. Supplemental F19s shall comply with COAs from previous spill reports (Doc# 402028230)

Date: 05/11/2019

Reportable: YES

GPS: Lat Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location: Comment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401705	FIR Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4819216