

**Beeson 3-21**

API # 05-063-6257

Ground Level = 4,309' (KB = 10')

Casing = 5-1/2"

PBSD: 5482'

Perfs = 5,415'-5,422',



---

**Beeson 3-21 P&A Procedure**

## Day 1

- 1) MI Codell Well Service and hold safety meeting
- 2) POOH with Tbg to derrick for what is needed to plug, lay down rest to be hauled.
- 3) RU Wireline, Set CIBP @ 5,400'. Dump 2 sks of Cement. CIBP 15' from perfs
- 4) RIH @ Perforate @ 450'
- 5) Trip in Hole with Plugging Stands and set 15 sks from 2250'-2350' to cover top section of Dakota formation
- 6) Squeeze 50 sks @ 450'. Leaving 100' in the casing
- 7) Set 20 sks of cement @ surface
- 8) RD Cementers, RDMO Codell Well Service
- 9) MIRU Welder, Cut Casing 5' below surface and weld plate.
- 10) Cleanup Location prepare for Reclamation of Surface Facility