

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2019

Submitted Date:

06/10/2019

Document Number:

693700187**FIELD INSPECTION FORM**Loc ID 417783 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****General Comment:**

COGCC Environmental Inspection. Well has been plugged, some surface equipment remains, partially buried produced water tanks have been removed without an approved Form 27.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment: Unused Steel Crude Oil AST remains on location, per Rule 1004.a. all surface equipment shall be removed within thre (3) months of well plugging						
Corrective Action:					Date:	

**Paint**

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:									
Corrective Action:								Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS		
OTHER		1	300 BBLS	STEEL AST			,		
Comment:	Portable steel tank remains on location, presumably from well plugging.								
Corrective Action:								Date:	

**Paint**

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					



**Environmental****Spill/Remediation:**

Comment: Two partially buried fiberglass produced water vessels were present on this location prior to well plugging. Operator has not submitted a Form 27 Site Investigation and Remediation Workplan, per Rule 905.b.

Corrective Action: Submit a Form 27 Site Investigation and Remediation Workplan with a proposal to perform a site assessment in the area of the removed produced water vessels

Date: 07/06/2019

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700188	Hillman9-1 Site Photos 6-6-2019	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4844926">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4844926</a>