



STATE OF COLORADO

Doc# 02573004
Email Correspondence
Facility ID 374696
20190614

Heil - DNR, John <john.heil@state.co.us>

Jolley 22-16 Inspection

5 messages

Heil - DNR, John <john.heil@state.co.us> Thu, Jun 13, 2019 at 3:31 PM
To: Mike Gardner <mgardner@terraep.com>
Cc: Alex Fischer - DNR <alex.fischer@state.co.us>, Richard Murray - DNR <g.richard.murray@state.co.us>, "Arauzo - DNR, Steven" <steven.arauza@state.co.us>

Hello Mike,

Upon inspection of the Jolley 22-16 pit and well pad, Steven and I observed some black fluids pooling below the union of an excavated flowline. FYI-if the fluids are the result of a leak then the line should be pressure tested before returning to service.



Thanks,

John Heil
Environmental Protection Specialist



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

C 970-787-0029 | P 303.894.2100 x5692 | O 970-625-1213
1818 Taughenbaugh Blvd., STE 103, Rifle, CO 81650
John.Heil@state.co.us | www.colorado.gov/cogcc

Mike Gardner <MGardner@terraep.com> Thu, Jun 13, 2019 at 4:02 PM
To: "Heil - DNR, John" <john.heil@state.co.us>

Cc: Alex Fischer - DNR <alex.fischer@state.co.us>, "g.richard.murray@state.co.us" <g.richard.murray@state.co.us>, "Arauzo - DNR, Steven" <steven.arauza@state.co.us>

John,

Thanks for sending the photo. I will run out right now and check on it to see if we have a leak of some sort. I can't see from the pic where this line is located, but I do not believe that this is associated with the pit that we're trying to close. I know they are doing some work on the south end of that pad, so I'll go see what I can find out.

Also, I have not been able to contact Mr. Kent Jolley yet regarding a discussion with him about the SAR/EC levels in the pit ... but I hope to hear from him soon. I will keep you guys posted on what I find out.

Thanks.

Mike Gardner

Cell: (970) 623-4875

Office: (970) 263-2760

mgardner@terraep.com

From: Heil - DNR, John <john.heil@state.co.us>

Sent: Thursday, June 13, 2019 3:32 PM

To: Mike Gardner <MGardner@terraep.com>

Cc: Alex Fischer - DNR <alex.fischer@state.co.us>; g.richard.murray@state.co.us; Arauzo - DNR, Steven <steven.arauza@state.co.us>

Subject: Jolley 22-16 Inspection

Hello Mike,

Upon inspection of the Jolley 22-16 pit and well pad, Steven and I observed some black fluids pooling below the union of an excavated flowline. FYI-if the fluids are the result of a leak then the line should be pressure tested before returning to service.



Thanks,

John Heil
Environmental Protection Specialist

[Redacted signature]

[Quoted text hidden]

Mike Gardner <MGardner@terraep.com>

Thu, Jun 13, 2019 at 4:29 PM

To: "Heil - DNR, John" <john.heil@state.co.us>

Cc: Alex Fischer - DNR <alex.fischer@state.co.us>, "g.richard.murray@state.co.us" <g.richard.murray@state.co.us>, "Arauzo - DNR, Steven" <steven.arauza@state.co.us>

John,

I just heard back from our construction supervisor and the "black fluid" that you see is simply a mastic (i.e., exterior coating) that is used for cathodic protection purposes. The mastic is spread over the bolts on the flange to help prevent them from rusting out. I also spoke with one of our guys who is out on that job right now and he assured me that this flange is not leaking.

The mastic is a thick, viscous, sticky material and it is a messy product to use. I will have the guys clean up any residual mastic that may be on the ground, but this is simply a protective exterior coating that is used on flanges, fittings, etc. that may be susceptible to corrosion.