

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/17/2019

Submitted Date:

06/17/2019

Document Number:

696101038

FIELD INSPECTION FORM

Loc ID 306483 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289213	WELL	PR	09/01/2018	OW	123-24766	TURMAN 32-42	PR

General Comment:

[This is a WELL & BATTERY inspection.](#)
[Well: Producing \(PR\).](#)
[Battery in operation.](#)
[Follow-up to Field Inspection Doc. #684903430 dated 04/06/2017.](#)

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Engine oil		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Good Housekeeping:			
Type			
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron pipe panel		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Braided wire		
Corrective Action:			Date:

Type	PUMP JACK		
Comment:	Metal wire mesh		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Gas engine		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	ECD #1: Controls crude oil tanks VOCs. ECD #2: Controls separator VOCs. Pilots: ON		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	2 - ECD scrubber pots 1 - Propane tank (Placarded).		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Prior insp: Stained soil at wellsite. Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition. Refer to Rule 605.d. Remove or remediate stained soil at wellsite. Comply w/ Rule 605.d. Original Corrective Action Date: 05/08/2017. This insp: * Stained soil at wellsite NOW appears mitigated. See photos #1, 2.		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	48 bbls.
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Shares berms w/ crude oil tanks.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.523124,-104.454009
Comment: Equalizer line connects crude oil tanks.					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Prior insp: Inadequate, low berms at Battery site. Refer to Rule 605.a.(4). Repair or install berms or other secondary containment devices at Battery site. Comply w/ Rule 605.a.(4). Original Corrective Action Date: 05/08/2017. This insp: * Berms appear to be rebuilt at Battery site. Containment NOW adequate. See photos #3, 4. Shares berms w/ produced H2O vault.				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			
			Date:

Inspected Facilities

Facility ID: 289213 Type: WELL API Number: 123-24766 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing \(PR\)](#).

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 06/17/2019 at approximately 13:45 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: TURMAN-67N63W /32NWSE Location ID: 306483 Location County: Weld County, Colorado While there, I observed: Well(s) - 1: Producing (PR). Battery in operation. Weather: Damp from prior rain.</p> <p>Follow-up to Field Inspection Doc. #684903430 dated 04/06/2017. 2 of 2: Corrective Actions appear addressed. 1.) Stained soil at wellsite. Mechanical conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition. Refer to Rule 605.d. Remove or remediate stained soil at wellsite. Comply w/ Rule 605.d. Original Corrective Action Date: 05/08/2017. * Stained soil at wellsite NOW appears mitigated. See photos #1, 2. 2.) Inadequate, low berms at Battery site. Refer to Rule 605.a.(4). Repair or install berms or other secondary containment devices at Battery site. Comply w/ Rule 605.a.(4). Original Corrective Action Date: 05/08/2017. * Berms appear to be rebuilt at Battery site. Containment NOW adequate. See photos #3, 4.</p> <p>NO: Corrective Actions observed on this Field Inspection report.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/17/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101039	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4852356