

<b>Operator:</b>	SRC Energy	<b>Reviewed: 7/1/19</b>	
<b>Well Name:</b>	MILLER K #25-31		
<b>Legal:</b>	SWNW 25 4N 66W		
<b>Location:</b>	Weld County, CO		
<b>API:</b>	05-123-29808		
<b>Surface:</b>	8.625" 24# @ 572'	<b>Hole Size: 12.25"</b>	<b>TOC: Surface</b>
<b>Production:</b>	4.5" 11.6# @ 7377'	<b>Hole Size: 7.875"</b>	<b>TOC: 2228' (CBL)</b>
<b>Perforations:</b>	7246-7262 CODELL	6948-7140 NIOBRARA	
<b>TD:</b>	7385		

P&R Procedure

1. Conduct pre-job safety meeting and complete daily JSA
2. Blow down well if necessary, circulate hole with treated water
3. Dig out around wellhead and perform bradenhead test
4. MIRU WO unit, ND wellhead, NU BOP, tally all pipe
5. TIH w/ 4-1/2" 11.6# CIBP on tubing, set at 6873'
6. Pressure test casing to 500 psi for 15 minutes
7. Set 15 sx on top of existing CIBP (190' plug)
8. Spot 300' 23 sx balanced plug from 4308 - 4008' MD
9. Cut 4.5" casing @ 900'
10. TIH with tubing to 950' and pump stub plug from 0 - 950'
  - a. pump 296 sks of 15.8# class G neat 1.15 cu./ft. yield cement
  - b. trip out of surface casing
  - c. Wait 4 hours and tag plug
11. RDMO WO unit
12. Dig up wellhead and cut off 10' below restored ground level, top off if necessary
13. Weld on cap with ID plate, inscribed with well location, and identity
14. Backfill, clean location
15. P&A complete