



SRC ENERGY

Reviewed: 7/9/19

<b>Operator:</b>	SRC Energy		
<b>Well Name:</b>	LH Miller Unit #1		
<b>Legal:</b>	NWNW, Section 25, Township 4N, Range 66W		
<b>Location:</b>	Weld County, CO		
<b>API:</b>	05-123-09118		
<b>Surface:</b>	8.625" 24# @ 493'	<b>Hole Size:</b> 12.25"	<b>TOC:</b> Surface
<b>Production:</b>	4.5" 11.6# @ 4,574'	<b>Hole Size:</b> 7.875"	<b>TOC:</b> 3575' Est (Calc)
<b>Perforations:</b>	4,438 – 4,476' (Sussex)		
<b>TD:</b>	4,584'		

#### P&R Procedure

1. Conduct pre-job safety meeting and complete daily JSA
2. Blow down well if necessary, circulate hole with treated water
3. Dig out around wellhead and perform bradenhead test
4. MIRU WO unit, ND wellhead, NU BOP, tally all pipe
5. TIH w/ 4-1/2 10.4# CIBP set at **4365'**
6. Run CBL from 4340' to surface
7. Pump 15 **sx** on top of CIBP
8. TIH to **2,500'** and perforate casing
9. TIH w/ 4-1/2" 10.5# CICR, set at **2,400'**
  - a. Squeeze perfs w/ **70 sx**
  - b. Release off of CICR and set **15 sx** on top
10. Cut 4.5" casing at **850'** and POOH
11. TIH to **900'** and pump stub plug
  - a. **295 sx** of 15.8# class G neat 1.15 cu./ft. yield cement
  - b. Pull into surface casing
  - c. Wait 4 hours and tag plug
12. RDMO WO unit
13. Dig up wellhead and cut off 10' below restored ground level, top off if necessary
14. Weld on cap with ID plate, inscribed with well location, and identity
15. Backfill, clean location
16. P&R complete