

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/17/2019

Submitted Date:

07/18/2019

Document Number:

697500334**FIELD INSPECTION FORM**
 Loc ID 319511 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
319511	LOCATION	AC			-	Zeiler SW-7 Pad	RI

General Comment:

This is a follow-up Interim Reclamation and Stormwater inspection to Doc. # 697500287 and in response to FIRR Doc. # 402111918.

Inspected Facilities									
Facility ID:	319511	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator has failed to install long-term stormwater BMPs. Some of the BMPs are temporary and have not been installed with good engineering practices. Wattles are not intended as a long-term BMP, only temporary (see photos 2, 4-5). A portion of the embankment berm of the sediment trap and ditch and berm BMP has not been properly stabilized and left unconsolidated (see photos 3-4). An unconsolidated BMP is not a proper functioning BMP, as the unconsolidated material becomes a source of potential pollution itself. In addition, a perimeter berm BMP appears to be intended to help direct stormwater to an inlet area along the western well pad perimeter- (see Photo 1). The berm BMP has not been compacted or otherwise stabilized.

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action remains open until resolved.

In addition, please submit a FIRR response with the following information of the installed wattles and erosion control blankets BMPs: purpose, description, application, material specifications, installation requirements and any other additional information.

Date: 06/10/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697500336	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4882619