

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
07/17/2019

Submitted Date:
07/18/2019

Document Number:
697500334

FIELD INSPECTION FORM

Loc ID 319511 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
319511	LOCATION	AC			-	Zeiler SW-7 Pad	RI

General Comment:

[This is a follow-up Interim Reclamation and Stormwater inspection to Doc. # 697500287 and in response to FIRR Doc. # 402111918.](#)

Inspected Facilities

Facility ID: 319511 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator has failed to install long-term stormwater BMPs. Some of the BMPs are temporary and have not been installed with good engineering practices. Wattles are not intended as a long-term BMP, only temporary (see photos 2, 4-5). A portion of the embankment berm of the sediment trap and ditch and berm BMP has not been properly stabilized and left unconsolidated (see photos 3-4). An unconsolidated BMP is not a proper functioning BMP, as the unconsolidated material becomes a source of potential pollution itself. In addition, a perimeter berm BMP appears to be intended to help direct stormwater to an inlet area along the western well pad perimeter- (see Photo 1). The berm BMP has not been compacted or otherwise stabilized.

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action remains open until resolved.

In addition, please submit a FIRR response with the following information of the installed wattles and erosion control blankets BMPs: purpose, description, application, material specifications, installation requirements and any other additional information.

Date: 06/10/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402113474	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4882654
697500336	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4882619