

# Inspection Photos

API: 05-055-06314

Operator: OXY USA INC

Inspection Date: 8/1/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019

## Inspection Photos



**Photo 1.** There is erosion occurring at the culvert with no outlet protection.  
No outlet protection has been installed at this culvert identified by previous inspection.  
Lat/Long:37.69799,-105.20237



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 2.** Rock check dams have been installed along the diversion ditch. These check dams are small and will likely fill in with sediment and will need ongoing maintenance. Lat/Long:37.69759,-105.201516



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 3.** Sediment has been cleaned out of the culverts inlet (left photo). Material was placed off to the side (right photo) and must be seeded and stabilized.

Lat/Long:37.69730,-105.19998



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 4.** Sediment has been cleaned out of the culverts outlet. Material was placed off to the side which must be seeded and stabilized.

Lat/Long:37.69730,-105.19998



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 5.** There were some noxious weeds along the pipeline that were wilted and others that were not treated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 6.** There were noxious weeds (Diffuse knapweed) behind the has compressor that were not treated.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 7.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 8.** The erosion and BMP's have been repaired. There are bare areas that need to be seed and revegetated.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 9.** The noxious weed in this are appear to have been sprayed. The Mullein and Houndstongue are biennials which will die at the end of season anyway during second year of growth. To control these weeds, seed heads should be collected and disposed of.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 10.** There are numerous non native Small burnet (*Sanguisorba minor*) plants growing in the interim reclamation area. The plants are not reflective of reference area vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 11.** The vegetation is establishing well in the interim reclamation area at the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019



## Inspection Photos



**Photo 12.** Northwest side of the location. Vegetation is well established in this area. The electric fence remains have been removed since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06314 | Date: 8/1/2019