

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2019

Submitted Date:

09/18/2019

Document Number:

693200406

FIELD INSPECTION FORM

Loc ID 334069 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Caerus		COGCC.inspections@caerusoilandgas.com	All Piceance inspections
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
466951	SPILL OR RELEASE	AC	09/03/2019		-	SHIDELER-68S93W 1SWNE	EG

General Comment:

Engineering Integrity Inspection performed on August 18, 2019. In response to Supplemental form 19 spill report Doc #402162155

Flowline was repaired and put back into at time of inspection.

Inspected FacilitiesFacility ID: 466951 Type: SPILL OR API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline DescriptionFlowline Type: Well SiteSize: 8"Material: Carbon SteelVariance: NoAge: 1-5 YrsContents: Produced WaterIntegrity Summary

Failures:

Spills: YesRepairs Made: Yes

Coatings:

H2S: No

Cathodic Protection:

Pressure TestingWitnessed: No

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: Carbon Steel section was cut out and replaced with Poly

Provide Root Cause when information becomes available. Via FIR Resolution and email to Western Integrity inspector

Provide pressure test results of repaired flowline before returning it to service. Via FIR Resolution and email to Western Integrity inspector

See photo log

Corrective Action:

Date: 09/25/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200407	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4941200