

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2019

Submitted Date:

10/31/2019

Document Number:

679705889

## FIELD INSPECTION FORM

 Loc ID 315411 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 6720  
 Name of Operator: ROBERT L BAYLESS PRODUCER LLC  
 Address: 621 17TH ST STE 2300  
 City: DENVER State: CO Zip: 80293
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments  
3 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230788	WELL	SI	07/01/2019	GW	103-08457	PHILADELPHIA CREEK-FED 39	SI

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 10-30-2019 at approximately 17:10, inspector Rick Moran, conducted a follow up inspection at Robert L Bayless well Philadelphia Creek 39in Rio Blanco county of FIR document 679704886.

The following compliance issues are uncompleted:

- 1) Stormwater going through location & pit. Photos 4 & 5. Complete by 8-28-2019.
- 2) Pit < 2' of freeboard. Photo 3. Complete by 8-28-2019.
- 3) Unmarked deadman. Photo 2. Complete by 8-28-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705889.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	One fallen deadman.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	08/28/2019
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230788 Type: WELL API Number: 103-08457 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					
Ditches	Fail					

**Comment:** Sediment is flowing onto the location from the south hillside. That sediment is accumulating on the location and some is flowing further off location to the north.  
 The south hillside has a ditch & berm along 1/2 of the base that is directing some stormwater away from the location. It appears that ditch has filled with sediment & the berm washed away next to the meter building, pit, and separator.  
 The fallen deadman appears to be associated with stormwater flow.

**Corrective Action:** Install or repair required BMPs per Rule 1002.f. **Date:** 08/28/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Type:** Blowdown      **Lined:** NO      **Pit ID:**      **Lat:** 39.917910      **Long:** -108.735970

**Reference Point:** \_\_\_\_\_      **Other:** \_\_\_\_\_      **Length:** \_\_\_\_\_      **Width:** \_\_\_\_\_

**Lining:**

**Liner Type:** \_\_\_\_\_      **Liner Condition:** \_\_\_\_\_

**Comment:** \_\_\_\_\_ **Date:** \_\_\_\_\_  
**Corrective**

**Fencing:**

**Fencing Type:** Wildlife      **Fencing Condition:** Adequate

**Comment:** \_\_\_\_\_ **Date:** \_\_\_\_\_  
**Corrective**

**Netting:**

**Netting Type:** \_\_\_\_\_      **Netting Condition:** \_\_\_\_\_

**Comment:** \_\_\_\_\_ **Date:** \_\_\_\_\_  
**Corrective Action**

**Anchor Trench Present:** \_\_\_\_\_      **Oil Accumulation:** NO      **2+ feet Freeboard:** NO

**Comment:** Pit has ~18" of freedboard. Evidence of stormwater loading pit with sediment.  
**Corrective**      Install or repair required BMPs per Rule 1002.f. **Date:** 08/28/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402228524	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978100">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978100</a>
679705890	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978097">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978097</a>