

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/11/2019

Submitted Date:

11/12/2019

Document Number:

687905819

FIELD INSPECTION FORMLoc ID 311909 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Inspections, All		inspections@catamountep.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216324	WELL	PR	08/26/1993	GW	067-07930	HARMON GAS UNIT A 2	PR
435727	WELL	PR	08/12/2017	GW	067-09901	IGE 141	PR

General Comment:

Operator was given corrective actions in previous field inspection reports for other locations (doc#'s 687903685, 687903691, 687904515, 687904515, 687904846, 687905609) for non-compliance and inadequate maintenance of secondary containment. Current liner is inadequate as evident by numerous holes and tears. This inspection is in response to DOC#687905075 on 07/02/2019 when liner had been repaired from previous inspection DOC#687904515 on 04/08/2019. Photos at the end of this inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign posted at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Company contact information posted. Missing local emergency services number or "911" on all signs.		
Corrective Action:	Update sign information per Rule 210.	Date:	12/12/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Secondary containment poly tarp liner has multiple tears and holes in liner base and on walls showing daylight at base from under steel secondary containment structure. Tires have been removed, liner is not adequate at time of inspection.			
Corrective Action:	Use adequate material or engineering to make secondary containment sufficiently impervious in order to comply with Rules 605.a(4) and 906.d			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 216324 Type: WELL API Number: 067-07930 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 435727 Type: WELL API Number: 067-09901 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402236832	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986005
687905820	IGE 141 inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986000