

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2020

Submitted Date:

04/22/2020

Document Number:

694400298

FIELD INSPECTION FORM

Loc ID 319067 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 39560
Name of Operator: TOP OPERATING COMPANY
Address: 3609 S WADSWORTH BLVD STE 340
City: LAKEWOOD State: CO Zip: 80235

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
HERRING, MURRAY J	(303) 727-9915 x203	murray.herring@topoperating.com	
Herring, Paul	303-727-9915	paul.herring@topoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242824	WELL	PR	12/01/2016	GW	123-10615	STAMP 31-2C	PR
426981	TANK BATTERY	AC	12/19/2011		-	Stamp 31-2 426981	AC

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 1	Comment: lubricator at wellhead	Corrective Action:	Date:	
Type: Gas Meter Run	# 1	Comment: XMV located on separator gasoline.	Corrective Action:	Date:	
Type: Emission Control Device	# 3	Comment:	Corrective Action:	Date:	
Type: Horizontal Heated Separator	# 1	Comment:	Corrective Action:	Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:	Production tank has fluid running down front of tank, pooling in the soil below. See photo#3 Production tank has fluid and buildup around backside drain valve, leaking onto soil. See photo #4				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: <u>05/22/2020</u>

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Comment: [production tank and water tank share berms](#)

Corrective Action: _____ Date: _____

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,

Comment: _____

Corrective Action: _____ Date: _____

Paint

Condition Adequate _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Comment: [Shares berms with produciton tank.](#)

Corrective Action: _____ Date: _____

Venting:

Yes/No _____

Comment: _____

Corrective Action: _____ Date: _____

Flaring:

Type _____

Comment: _____

Corrective Action: _____ Date: _____

Inspected Facilities

Facility ID: 242824 Type: WELL API Number: 123-10615 Status: PR Insp. Status: PR

Producing Well

Comment: Well appears to SI at well head ground valve.

Corrective Action: _____ Date: _____

Facility ID: 426981 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: Well SI at time of inseption. No presure observed on vessel.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p><u>COGCC Inspection Report Summary</u> On Wednesday, April 22, at approximately 14:22, I, Supervisor Adam Kraich, conducted an on-site inspection at the Stamp 31-2C, located in Longmont, Weld County, Colorado.</p> <p>While there, I observed the well head and production facility in a shut in state of operation. During this inspection the following possible compliance issues were observed: Fluid present at the front of the production tank, reaching the soil below, along with fluid present near and around the production tank backside drain valve. See attached photos for details.</p> <p>I performed an FLIR audit of the location at time of inspection. See attached video(s) for detail.</p> <p>A follow up on this site inspection needs to be conducted to ensure the This is a summary of inspection report.</p>	kraicha	04/22/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402378341	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5129977
694400299	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5129958
694400300	FLIR audit, facility	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5129959
694400301	FLIR audit, Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5129960