

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/28/2020

Submitted Date:

04/30/2020

Document Number:

693700435**FIELD INSPECTION FORM**Loc ID 444078 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Young, Rob		rob.young@state.co.us	
Neighbors, Cory		cneighbors@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415877	LOCATION	AC	03/27/2020		-	Randall Creek 29 SESE	EI
475858	SPILL OR RELEASE	AC			-	Randall Crk 29 prod H2O line	EI

General Comment:

Inspected Facilities									
Facility ID:	<u>415877</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>475858</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Environmental**Spill/Remediation:**

Comment: COGCC Inspection response to Spill ID 475858, above ground produced water line. Leg of affected line has been replaced with stainless steel (photo). Spill affected an area around produced dumlins and several hundred feet in an east-west direction directly north of dumlins. A stormwater pond near the topsoil stockpile on north end of pad was apparently affected. No offsite impacts were observed. Approximately 10 yards impacted soil removed and stockpiled on location.

Corrective Action: Submit Form 19 Supplemental Report with map of the spill area extent along with pH, EC and SAR laboratory analytical data from background and spill area soil samples by June 5, 2020 as directed in approved Form 19-I/S. Include analysis for TPH (C6-36) and BTEX of soil samples from spill area. Include root cause for corrosion of produced water dumlins.

Date: 06/05/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402387466	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139280
693700436	Soil stockpile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139261
693700437	Spill area looking east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139262
693700438	Stormwater pond adjacent topsoil pile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139263
693700439	Spill area looking west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139264
693700440	Produced Water dumlins replaced with SS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5139265