

FORM

6

Rev  
02/20

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE

ET

OE

ES

Replug By Other Operator

Document Number:

402449262

Date Received:

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175

Contact Name: Valerie Danson

Name of Operator: PDC ENERGY INC

Phone: (970) 506-9272

Address: 1775 SHERMAN STREET - STE 3000

Fax:

City: DENVER State: CO Zip: 80203

Email: valerie.danson@pdce.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-123-07326-00

Well Name: LESSER

Well Number: 1

Location: QtrQtr: NENE

Section: 21

Township: 5N

Range: 66W

Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

## Only Complete the Following Background Information for Intent to Abandon


Latitude: 40.390390

Longitude: -104.778620

GPS Data: GPS Quality Value: 1.6 Type of GPS Quality Value: Date of Measurement: 05/05/2020

GPS Instrument Operator's Name: Scott Sherard

Reason for Abandonment:


☐ Other

Casing to be pulled:



Estimated Depth:

Fish in Hole:



If yes, explain details below

Wellbore has Uncemented Casing leaks:



If yes, explain details below

Details:

## Current and Previously Abandoned Zones

Formation

Perf. Top

Perf. Btm

Abandoned Date

Method of Isolation

Plug Depth

Total: 0 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	165	160	165	0	VISU
OPEN HOLE	7+7/8			7,846				

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	126	sks cmt from	6950	ft. to	6321	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	265	sks cmt from	4136	ft. to	3217	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set	230	sks cmt from	1739	ft. to	879	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set		sks cmt from		ft. to		ft.	Plug Type:		Plug Tagged:	<input type="checkbox"/>
Set		sks cmt from		ft. to		ft.	Plug Type:		Plug Tagged:	<input type="checkbox"/>

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 169 sacks half in. half out surface casing from 579 ft. to 0 ft. Plug Tagged: ☒

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. \_\_\_\_\_ inch casing Cut and Cap Date: 06/23/2020  
 of \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: NexTier

Type of Cement and Additives Used: Class G 15.8 PPG Cement & Type III 14.8 PPG Portland Cement

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

#### Technical Detail/Comments:

Lesser 1 (05-123-07326)/Re-Enter to Re-Plug Procedure  
 Original Plug Date: 6/8/1971  
 Producing Formation: N/A (DA well)  
 Upper Pierre Aquifer: 470'-1470'  
 TD: 7846'  
 Surface Casing: 8 5/8" 24# @ 165' w/ 160 sxs cmt  
 Open Hole: 7 7/8" @ 7846'  
 Existing Plugs: 390'-116' (95 sx cmt), 20' to Surface (10 sx cmt)  
 Procedure:  
 1. Dig out to find wellhead and check pressure.  
 2. Cut cap off, extend surface pipe to achieve ground level.  
 3. MIRU WO unit, ND wellhead, NU BOP, tally all pipe to be ran in well.  
 4. Mill cement, cement btm is approximately 390' according to well history data.  
 5. Wash run down to top of Niobrara @ 7000'.  
 6. PU tubing to 6950'. RU cementing company. Mix and pump 126 sxs 15.8#/gal CI G cement down tubing (Nio coverage 6950'-6450'). PU tubing above plug and SI well. (Top of Niobrara @ 7000')  
   a. Wait 4 hours and tag plug. TOC tagged at 6321'.  
 7. PU tubing to 4136'. RU cementing company. Mix and pump 265 sxs 15.8#/gal CI G cement down tubing (Sussex coverage 4120'-3620'). PU tubing above plug and SI well. (Top of Sussex @ 4170')  
   a. Wait 4 hours and tag plug. TOC tagged at 3217'.  
 8. PU tubing to 1739'. RU cementing company. Mix and pump 230 sxs 14.8#/gal Type III cement down tubing (Pierre Aquifer coverage 1720'-1220'). PU tubing above plug and SI well.  
   a. Wait 4 hours and tag plug. TOC tagged at 879'.  
 9. PU tubing to 579'. RU cementing company. Mix and pump 169 sxs 14.8#/gal Type III cement down tubing. Cement circulate to surface.  
 10. RDMO WO unit. Remove extension of surface pipe.  
 11. Weld on cap with ID plate, inscribed with well location, and identity. Backfill, clean location, Re-Entry complete.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: Valerie Danson

Title: Reg Tech

Date: \_\_\_\_\_

Email: valerie.danson@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_

**COA Type**

**Description**

--	--

**Attachment Check List**

**Att Doc Num**

**Name**

402449263	CEMENT JOB SUMMARY
402449264	OPERATIONS SUMMARY
402449265	WELLBORE DIAGRAM

Total Attach: 3 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)