

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/04/2020

Submitted Date:

08/04/2020

Document Number:

698100159

FIELD INSPECTION FORM
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 Arauza, Steven 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Trujillo, Aaron		aaron.trujillo@state.co.us	
,		cogccnotifications@laramie-energy.com	All inspections
Bankert, Wayne		wbankert@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
468517	SPILL OR RELEASE	CL	06/29/2020		-	Kobe-Chevron Valve Can	EI

General Comment:

COGCC Environmental Inspection conducted along with Reclamation Inspector A. Trujillo. Follow-up to Remediation Project #14368 and operator's eForm 27 doc #402442807. Weather conditions during inspection were cloudy/overcast with a temperature of 74 degrees Fahrenheit.

Remediation Project #14368 documents operator's efforts to remediate impacts resulting from Spill/Release ID #468517. See doc #402442813 for Operator's report of the June 2020 re-sampling event and vegetation monitoring event.

Inspectors observed vegetative growth and soil conditions along reported flow path from the valve can/point of release, along the north and south sides of S Dry Fork Road, to the natural drainages approximately 1000' east of the valve can. Neither obviously distressed vegetation nor salt staining were observed during inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Operator's Remediation Report (doc #402442813) states that "Leftover haybales placed inside the stormwater drainage should be removed to eliminate pooling and allow stormwater to flow to its final destination (irrigation ditch) after closure of the project." On inspection date, wooden stakes were observed at one hay bale location. See photos.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f.		Date: 08/21/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	Valves observed on flowline riser at valve can were neither locked out nor tagged out. See photos.		
Corrective Action:	Lock and tag out valves to prevent spills/releases per Rule 1102.i.		Date: 08/21/2020

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 468517 Type: SPILL OR API Number: - Status: CL Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402459501	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5216512
698100161	20200804 field photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5216506