

Inspection Photos

API: 043-06221

Operator: AUSCO PETROLEUM INC

Inspection Date: 10/19/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06221 | Date: 10/19/2020

Inspection Photos



Photo 1. Facing southwest along the access road. Stormwater from the road is creating erosion in area shown at red arrow.. The wattles placed in this area are displaced and are not controlling erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 10/19/2020

Inspection Photos



Photo 2. There is erosion along the access road. Stormwater is diverted down the road and into drainage area shown in previous photo. The erosion needs to be repaired and stormwater needs to be properly diverted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 10/19/2020

Inspection Photos



Photo 3. Facing south toward the location. The fence around the vegetated area is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 10/19/2020

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 10/19/2020

Inspection Photos



Photo 5. There are wattles displaced at the southwest side of the location. This was also observed in the previous inspection. Wattles need to be repired and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 10/19/2020

Inspection Photos



Photo 6. There is an erosion channel at the southwest side of the location. Stormwater is directed to this area from the top perimeter dictated. BMP's are needed in this area to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 10/19/2020

Inspection Photos



Photo 7. The well sign is posted at the pumpjack.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 10/19/2020

Inspection Photos



Photo 8. The top perimeter ditch is directing stormwater toward the road which has deposited sediment onto the road. BMP's are needed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 10/19/2020

Inspection Photos



Photo 9. There is erosion occurring across the road at the north side of the location caused by stormwater directed from the top perimeter ditch shown in the previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 10/19/2020