

Inspection Photos

Operator: Logos Operating
API: 067-08365
Date: 3/9/2021



Photo 1. View of the project area from the northeastern corner facing center.




Photo 2. View of erosional channel forming within the northeastern project area, where stormwater flows off of the working area. Channel is approximately 18 inches wide and 6 inches deep.



Photos 3. View of erosional channel in the southern project area, approximately 18 inches wide and 10 inches deep. Gravel placed in area is not adequate BMP.



Photo 4. View of erosional channel in diversion that runs adjacent to the southern project area. Additional stabilization measures are needed here, such as channel lining.



Photo 5. View of culvert outlet along the access road. Stabilization is needed around the culvert and where outflows are resulting in head-cutting from the culvert.



Photo 6. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, and Indian ricegrass.



Photo 7. View of the reference area comprised of pinyon and juniper woodland, with understory of grasses and forbs such as Palmer's penstemon and Indian ricegrass.