

FORM  
6Rev  
11/20

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402637472

Date Received:

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10110

Contact Name: Kapri McMillan

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Phone: (970) 364-2826

Address: 1001 17TH STREET #2000

Fax:

City: DENVER

State: CO

Zip: 80202

Email: kmcmillan@gwp.com

**For "Intent" 24 hour notice required,**

Name: Santistevan, Brittani

Tel: (720) 471-1110

**COGCC contact:**

Email: brittani.santistevan@state.co.us

Type of Well Abandonment Report: ☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

API Number 05-123-12952-00

Well Name: PIERCE UNIT-KENNEDY

Well Number: 3

Location: QtrQtr: NESW

Section: 27

Township: 8N

Range: 66W

Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: PIERCE

Field Number: 69000

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.631210

Longitude: -104.765830

GPS Data: GPS Quality Value: 6.0 Type of GPS Quality Value: Date of Measurement: 04/10/2006

Reason for Abandonment: ☐ Dry ☒ Production Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes☒ No

Estimated Depth:

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☒ No

If yes, explain details below

Details:

## Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|-----------|-----------|-----------|----------------|---------------------|------------|
| LYONS     | 9214      | 9270      |                |                     |            |

Total: 1 zone(s)

## Casing History

| Casing Type | Size of Hole | Size of Casing | Grade | Wt/Ft | Csg/Liner Top | Setting Depth | Sacks Cmt | Cmt Btm | Cmt Top | Status |
|-------------|--------------|----------------|-------|-------|---------------|---------------|-----------|---------|---------|--------|
| CONDUCTOR   | 20           | 16             | NA    | 84    | 0             | 63            | 40        | 63      | 0       | CALC   |
| SURF        | 12+1/4       | 9+5/8          | NA    | 47    | 0             | 1001          | 400       | 1001    | 0       |        |
| 1ST         | 7+7/8        | 5+1/2          | NA    | 15.5  | 0             | 9327          | 1455      | 9327    | 7450    | CBL    |

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 9160 with 25 sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 18 sks cmt from 7000 ft. to 6700 ft. Plug Type: CASING Plug Tagged: ☐  
Set 12 sks cmt from 4600 ft. to 4500 ft. Plug Type: CASING Plug Tagged: ☐  
Set 12 sks cmt from 1600 ft. to 1500 ft. Plug Type: CASING Plug Tagged: ☐  
Set 145 sks cmt from 1200 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at 7100 ft. with 40 sacks. Leave at least 100 ft. in casing 7000 CICR Depth

Perforate and squeeze at 4700 ft. with 52 sacks. Leave at least 100 ft. in casing 4600 CICR Depth

Perforate and squeeze at 1700 ft. with 52 sacks. Leave at least 100 ft. in casing 1600 CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing

Surface Plug Setting Date: \_\_\_\_\_ Cut and Cap Date: \_\_\_\_\_ Number of Days from Setting Surface Plug to Capping or Sealing the Well: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

Perf @ 1200' squeeze 255 sx cmt to surface in the annulus

Procedure:

- 1 Contact COGCC
- 2 MIRU
- 3 Pull pump and rods
- 4 NDWH/NUBOP
- 5 RIH w/ CIBP and set @ 9160'
- 6 Pump 25 sx Thermal 35 on top of plug at 9160', ETOC 8896'
- 7 TOOH, LD to ~7000', stand back remaining
- 8 RIH w/ WL and shoot holes at 6900' & 7100'
- 9 RIH and set CICR @ 7000'
- 10 Squeeze 40 sx thru CICR, leave additional 18 sx on top Thermal 35, ETOC 6700'
- 11 Roll hole clean
- 12 TOOH, LD to ~4600', stand back remaining
- 13 RIH w/ WL and shoot holes at 4500' & 4700'
- 14 RIH and set CICR @ 4600'
- 15 Squeeze 52 sx thru CICR, leave additional 12 sx on top Class G +2%CC, ETOC 4500'
- 16 Roll hole clean
- 17 TOOH, LD to ~1600', stand back remaining
- 18 RIH w/ WL and shoot holes at 1500' & 1700'
- 19 RIH and set CICR @ 1600'
- 20 Squeeze 52 sx thru CICR, leave additional 12 sx on top Class G +2%CC, ETOC 1500'
- 21 Roll hole clean
- 22 Shoot holes at 1200' and establish circulation up annulus
- 23 Circulate 255 sx Class G + 2% CC up annulus to surface, fill casing from 1200' to surface with 145 sx
- 24 WOC 4 hours
- 25 RIH tag, top off w/ cement as needed
- 26 RDMO
- 27 Cut & cap casing 4' - 6' below GL w/ plate (Well Name, API, Legal Location)

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Renee Kendrick  
Title: SR Regulatory Analyst Date: \_\_\_\_\_ Email: rkendrick@gwp.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Date: \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_ Expiration Date: \_\_\_\_\_

**COA Type** **Description**

|  |  |
|--|--|
|  |  |
|--|--|

**Attachment List**

| <b>Att Doc Num</b> | <b>Name</b>      |
|--------------------|------------------|
| 402637520          | WELLBORE DIAGRAM |
| 402637541          | WELLBORE DIAGRAM |
| 402638599          | WELLBORE DIAGRAM |
| 402638601          | WELLBORE DIAGRAM |

Total Attach: 4 Files

### General Comments

| <u>User Group</u> | <u>Comment</u>   | <u>Comment Date</u> |
|-------------------|--|---------------------|
| Permit            | <ul style="list-style-type: none"><li>-Confirmed as-drilled well location.</li><li>-No other forms in process.</li><li>-Production reporting up-to-date.</li><li>-Confirmed productive interval docnum: 254198.</li><li>-Incorrected WBDs.</li><li>-Returned to draft.</li></ul> | 03/24/2021          |

Total: 1 comment(s)