

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2021

Submitted Date:

05/05/2021

Document Number:

693700772**FIELD INSPECTION FORM**Loc ID 323578 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone | Email                     | Comment                             |
|------------------|-------|---------------------------|-------------------------------------|
| Axelson, John    |       | john.axelson@state.co.us  |                                     |
| MacLaren, Joe    |       | joe.maclaren@state.co.us  |                                     |
| Ferrin, Jeremy   |       | jeremy.ferrin@state.co.us |                                     |
| Inspections, KPK |       | cogcc@kpk.com             | <a href="#">All KPK Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type             | Status | Status Date | Well Class | API Num   | Facility Name                   | Insp Status |
|-------------|------------------|--------|-------------|------------|-----------|---------------------------------|-------------|
| 245427      | WELL             | PR     | 10/01/2018  | OW         | 123-13222 | LONGMONT FARMS UNIT 5           | EI          |
| 479267      | SPILL OR RELEASE | AC     | 01/29/2021  |            | -         | Longmont Farms Unit #5 Flowline | EI          |

**General Comment:**[COGCC Inspection of Spill ID 479267 and followup to Field Inspection Report 693700764](#)

| Inspected Facilities |               |       |                 |             |                  |         |           |               |           |
|----------------------|---------------|-------|-----------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID:         | <u>245427</u> | Type: | <u>WELL</u>     | API Number: | <u>123-13222</u> | Status: | <u>PR</u> | Insp. Status: | <u>EI</u> |
|                      |               |       |                 |             |                  |         |           |               |           |
| Facility ID:         | <u>479267</u> | Type: | <u>SPILL OR</u> | API Number: | <u>-</u>         | Status: | <u>AC</u> | Insp. Status: | <u>EI</u> |
|                      |               |       |                 |             |                  |         |           |               |           |

**Environmental****Waste Management:**

| Type              | Management   | Condition | GPS (Lat) | (Long) |
|-------------------|--|-----------|-----------|--------|
| Oily Soil         | Piles  | Adequate  |           |        |
| Comment           | Approximately 10-20 yards of presumably impacted soil are stockpiled on locatino with earthen containment berm |           |           |        |
| Corrective Action |  |           |           | Date:  |

**Spill/Remediation:**

|                    |  |  |  |                  |
|--------------------|--|--|--|------------------|
| Comment:           | Operator has initiated an excavation at flowline release. Excavation is currently approximately 45' x 15' x 10' and remains unchanged since previous inspection. Standing water is present in excavation and stormwater runs into east and north side of excavation. Excavation is fenced with cattle panels on all sides. Spill was discovered 1/19/2021 and resolution was required by 4/19/2021. Form 19-S submitted indicates flowline is fiberglass and was replaced with new fiberglass section fused to existing line. This does not match field observations |  |  |                  |
| Corrective Action: | Operator to submit Form 27 with Site Investigation and Remediation Workplan for remediation of Spill (this was due by April 19, 2021). Operator to submit Form 19 Supplemental Report with root cause and corrective action for flowline failure and resolution of Spill via Work proceeding under a Form 27. Operator to submit results of flowline repair pressure test on Form 19 Supplemental Report. Operator to improve stormwater controls to prevent further contamination of groundwater from stormwater run-in. All actions are overdue.                   |  |  | Date: 04/28/2021 |

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                   | URL   |
|--------------|-------------------------------|---|
| 693700777    | LongmontFarms5Photos_5-5-2021 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421719">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421719</a> |