

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2021

Submitted Date:

05/13/2021

Document Number:

693700789**FIELD INSPECTION FORM**Loc ID 323578 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245427	WELL	PR	10/01/2018	OW	123-13222	LONGMONT FARMS UNIT 5	EI
479267	SPILL OR RELEASE	AC	01/29/2021		-	Longmont Farms Unit #5 Flowline	EI

General Comment:[COGCC Inspection of Spill ID 479267 and followup to Field Inspection Report 693700772](#)

Inspected Facilities									
Facility ID:	245427	Type:	WELL	API Number:	123-13222	Status:	PR	Insp. Status:	EI
Facility ID:	479267	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Adequate		
Comment	Operator conducting dig and haul; onsite personnel states no stockpiles will remain on surface			
Corrective Action				Date:

Spill/Remediation:

Comment:	Operator has initiated an excavation at flowline release. Excavation is currently approximately 45' x 15' x 10'. Operator was onsite at time of inspection continuing to excavate eastern side and base of excavation. It appears standing water in excavation is stormwater - eastern side of excavation was dry at base. Operator deploys cattle panels to fence excavation when personnel not present. Spill was discovered 1/19/2021 and resolution was required by 4/19/2021. Form 19-S submitted indicates flowline is fiberglass and was replaced with new fiberglass section fused to existing line. This does not match field observations.			
Corrective Action:	Operator to submit Form 27 with Site Investigation and Remediation Workplan for remediation of Spill (this was due by April 19, 2021). Operator to submit Form 19 Supplemental Report with root cause and corrective action for flowline failure and resolution of Spill via Work proceeding under a Form 27. Operator to submit results of flowline repair pressure test on Form 19 Supplemental Report.			Date: 04/28/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700795	LongmontFarms5Photos5-12-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5428110