

OCCIDENTAL PETROLEUM CORPORATION

Please contact your area engineer with any questions concerning this procedure.

6/2/2021

PLUG and ABANDONMENT PROCEDURE

WARDELL 33-6

API: 05-123-24086



Step Description

1	Review Previous Open Wells Reports/Well History. If you have questions or concerns, contact Foreman/Engineer.
2	COA: Provide 48 hour notice to COGCC prior to rig up per request on approved Form 6 (e.g. call field coordinator, submit Form 42, etc.).
3	Notify Automation Removal Group at least 24 hours prior to rig move. Request they catch and remove plunger, isolate production equipment, and remove any automation prior to rig MIRU.
4	MIRU Slickline. Pull production equipment and tag bottom. Record tag depth, casing/tubing pressures and fluid level in Open Wells. Directional Survey was run on 09/01/06. RDMO Slickline.
5	Prepare location for base beam equipped rig. Install perimeter fence as needed.
6	COA: Verify Form 17 (State Bradenhead Test) has been run within 60 days of RU.
7	Refer to the Rockies Well Services Guidelines document whenever rigging up BOP and WL, or whenever tripping in or out of the well. Consult with Foreman/Engineer before deviating from these guidelines.
8	Upon RU, check and record bradenhead pressure. If bradenhead valve is not accessible, re-plumb so that valve is above GL. Blow down bradenhead and leave open during working hours. Re-check pressure each day and input value in the "Casing press." box in Open Wells.
9	MIRU WO rig. Verify BOP and wellhead rating, inspect for appropriate API standards, pressure test BOP. Kill well as necessary using biocide treated fresh water. ND WH. NU BOP. Unland tbg. **Barrier Management** Fluid will be the only barrier while NU BOP. Stop and review JSA.
10	TOOH and SB 825' of 2-3/8" tbg. LD remaining 2-3/8" tbg.
11	MIRU WL. PU and RIH with (4-1/2", 11.6#) gauge ring to 7160'. POOH.
12	PU and RIH with (4-1/2", 11.6#) CIBP and set at +/- 7150' (collars at 7140' & 7182'). POOH. Slowly top fill well to clear out all gas. Pressure test CIBP to 500 psi. RIH and dump 2 sx cement on CIBP. POOH.
13	PU and RIH with (4-1/2", 11.6#) CIBP and set at +/- 4270' (collars at 4260' & 4302'). POOH. RIH and dump 2 sx cement on CIBP. POOH. RDMO WL.
14	COA: Confirm and document static conditions in the well before placing the next plug. If there is evidence of pressure or fluid migration at any time after placing the Sussex plug, contact Engineering.
15	PU and RIH with one 4', 3-1/8" perf gun with 4 spf. Shoot 16 squeeze holes at 2000'. RDMO WL.
16	Establish circulation down the casing and out the bradenhead with treated water. Reverse circulate as needed. Use slugs of mud thinner and surfactant if required. Continue to circulate until the hole is clean.
17	MIRU cementers. Pump Squeeze: 110 sx (24.1 bbl or 136 cf) of the Upper AGM blend (2% CaCl & 4% Gyp, 15.8 ppg & 1.23 cf/sx) down the casing. Volume is based on 300' in the casing-hole annulus with 50% excess, and 300' in the casing. Displace cement with Water to 1700'. Collect wet and dry samples of cement to be left on rig. RDMO Cementers.
18	Leave valves open for 10 minutes to allow cement to balance between the production and surface casing. If 2 bbls or more of displacement fluid flows back through the production casing, shut in well to ensure TOC remains at a workable depth.
19	COA: WOC 8 hours. If there is evidence of pressure or fluid migration, contact Engineering as there will need to be additional remediation attempts before the SC shoe plug.
20	TIH with 2-3/8" tubing and tag cement top to verify TOC inside production casing. TOOH and SB 825' of tubing.
21	PU and TIH with mechanical cutter on 2-3/8" tbg. Cut 4-1/2", 11.6# casing at 825'. TOOH and LD cutter.
22	Attempt to establish circulation and circulate (58 bbl) with biocide treated fresh water.
23	ND BOP. ND TH. Un-land casing. Rig max pull shall be 100,000#. Max pull over string weight shall be 50,000#. If unable to unland, contact Foreman/Engineer. **Barrier Management** Fluid will be the only barrier while unlanding casing. Stop and review JSA.

24	Install BOP on casing head with 4-1/2", 11.6# pipe rams. **Barrier Management** Fluid will be the only barrier while NU BOP. Stop and review JSA.
25	TOOH and LD all 4-1/2", 11.6# casing. Remove 4-1/2", 11.6# pipe rams and install 2-3/8" pipe rams.
26	TIH with mule shoe on 2-3/8" tubing to 825'. Establish circulation to surface with biocide treated fresh water and pump at least three hole-volumes (175.5 bbl) to clean up wellbore.
27	COA: Verify and document that all pressure and fluid migration has been eliminated prior to placing the SC shoe plug at 825'. If there is evidence of pressure or fluid migration, contact Engineering.
28	MIRU cementers. Pump 10 bbls (min) of pre-flush, followed by 5 bbls fresh water spacer. Pump Stub Plug: Pump 120 sx (26.3 bbl or 148 cf) of the Upper AGM blend (2% CaCl & 4% Gyp, 15.8 ppg & 1.23 cf/sx). Volume is based on 102' in 7.875" bit size open hole with 100% excess factor. 203' in the 8-5/8", 24# surface casing with no excess. The plug is designed to cover 825'-520'. Collect wet and dry samples of cement to be left on rig. RDMO Cementers. Notify engineering if circulation is ever lost during job.
29	COA: If cement was not circulated to surface, then WOC 4 hours. Tag TOC. TOC must be 673' or shallower. If tag is too deep or there is evidence of pressure or fluid migration, contact Engineering.
30	Pull out of cement. TOOH to 120'. Reverse circulate tbg clean. WOC.
31	TIH and tag cement to verify appropriate coverage above the surface casing shoe. Consult with Foreman/Engineer on when to PT casing. Pressure test casing to 500 psi and hold for 15 minutes. Notify engineering if tag is low or pressure test fails.
32	TOOH. Lay down all tbg. ND BOP. Install night cap. RDMO WO rig.
33	Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries to rscDJVendors@anadarko.com within 24 hours of completion of the job.
34	Supervisor submit paper copies of all invoices, logs, and reports to VWP Engineering Specialist.
35	Excavation crew to notify One Call to clear excavation area around wellhead and for flow lines.
36	Excavate hole around surface casing enough to allow welder to cut casing a minimum 5' below ground level.
37	Welder cut casing minimum 5' below ground level.
38	Fill 8-5/8", 24# surface casing from 50' to surface with 16 sx (3.3 bbl or 19 cf) of cement (15.8 ppg & 1.15 cf/sx).
39	Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
40	Obtain GPS location data as per COGCC Rule 215 and send to rscDJVendors@anadarko.com.
41	Properly abandon flow lines per Rule 1103. File electronic Form 42 once abandonment is complete.
42	Back fill hole with fill. Clean location, and level.
43	Submit Form 6 to COGCC ensuring to provide 'As performed' WBD identifying operations completed.