

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2021

Submitted Date:

06/02/2021

Document Number:

697601365

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
GINTAUTAS, PETER 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	
Knop, Max	303-825-4822	MKnop@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479834	SPILL OR RELEASE	AC	04/28/2021		-	Suckla Farms E #2 Flowline	EI

**General Comment:**

steel panel fencing around spill area still in place as shown in attached photo.

Sorbent booms observed in main excavation in effort to minimize transport of crude oil in precipitation event but free product is visible floating on ponded water as shown in attached photo. Impacts to waters of the state are present from contact of free product with recent precipitation.

No barrier to prevent infiltration of crude oil and associated impacts to deeper soils and to shallow groundwater at site as likely happened in recent precipitation event.



**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 50

Comment:

PREVIOUS CORRECTIVE ACTIONS REQUIRED THAT FREE HYDROCARBONS MUST BE REMOVED AND THE MIGRATION OF IMPACTS BE LIMITED Free hydrocarbons are present floating on puddles of recent precipitation. Sorbent booms have not been effective at removing free oil from depressions and minimizing impacts to waters of the state including groundwater

Corrective Action: free product must be removed within 24 hours of this notice

Date: 06/03/2021

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_

Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402706804	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445806">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445806</a>
697601366	steel panel fence	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445800">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445800</a>
697601367	sorbent booms ineffective in removing free product	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445801">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445801</a>
697601369	looking north over approx. 80 foot length of spill excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445802">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5445802</a>