

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/27/2021

Submitted Date:

07/27/2021

Document Number:

689501304

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Findings:

4 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
,		mknop@kpk.com	
Graber, Nikki		nikki.graber@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480275	SPILL OR RELEASE	AC	07/09/2021		-	E. Stieber Consolidation	EI

General Comment:

Environmental inspection of E. Stieber Consolidation Spill (COGCC ID 480275(AC)/Complaint Doc #200449776) conducted 7/27/21. Inspections previously submitted under API 05-123-10115. At the time of inspections crews were on site backfilling clean imported soils into impacted groundwater and free product.

[Photos attached to document site conditions.](#)

Inspected Facilities

Facility ID: 480275 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Spill excavation is open and actively being backfilled (approx 10'x20'x8'). Impacted groundwater and free product were observed in the excavation and soil impacts remained in-situ (Photo 4). Excavator operator indicated that they were backfilling temporarily to allow for crews to repair the damaged pipeline and return it to service.

Corrective Action: Immediately remove pooled product from excavation in accordance with Rule 912.a.(2). In accordance with Rule 912.a.(6) No later than 90 days after a Spill or Release is discovered Operator will submit a Form 19 Supplemental requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate closure or a Form 27 Workplan with a timeline for investigation and closure of this release. If Remediation will continue under an approved Form 27, also submit a Form 19 ±Supplemental requesting closure of this spill referencing the approved Remediation workplan (10/4/21). Operator will provide notice to COGCC EPS Kari Brown (kari.l.brown@state.co.us) at least 48 hours prior to backfill or any sampling events performed on location. Note that samples collected must be analyzed for Table 915-1 parameters. On the next Form 19 subsequent operator is to provide the root cause of the incident and preventative measures that will be taken to prevent reoccurrence on this and other flowlines at this location. Please give the location of the failure (i.e. 6 O'clock position) and if the root cause is corrosion explain if it is external or internal. Please also list the wells associated with this facility on the form 19 subsequent.

Date: 10/04/2021

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)
Oily Soil	Other	Inadequate	
Comment	Pooled product was noted in the excavation on 7/9, 7/12, 7/20, and 7/27 and soil impacts remained visible in-situ on all sidewalls on 7/27.		
Corrective Action	Immediately remove pooled product from excavation in accordance with Rule 912.a.(2).		Date: <u>07/16/2021</u>

Spill/Remediation:

Comment: _____
 Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501305	Field Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5490492