

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402801971

Date Received:

09/03/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beardslee, Tom</u>		<u>tom.beardslee@state.co.us</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>efitzgerald@ogrisop.com</u>
<u>O'Shields, Charlie</u>	<u>940-682-5030</u>	<u>coshields@ogrisop.com</u>
<u>Atwater, Bonnie</u>	<u>432-755-0212</u>	<u>batwater@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 700600289

Inspection Date: 08/27/2021

FIR Submit Date: 08/31/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309123

Location Name: GOLDEN EAGLE-633S67W Number: 29SENW County: LAS ANIMAS

Qtrqtr: SENW Sec: 29 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.144806 Longitude: -104.913459

FACILITY - API Number: 05-071- -00 Facility ID: 288298

Facility Name: GOLDEN EAGLE Number: 29-6

Qtrqtr: SENW Sec: 29 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.144806 Longitude: -104.913459

CORRECTIVE ACTIONS:

1 CA# 155339

Corrective Action: Operator shall sample liquid in pit for COGCC Table 915-1 Organic Compounds in Groundwater and TPH (C6-C36) and submit via Field Inspection Resolution Request (FIRR) in response to this inspection. Corrective Action date is for collecting samples.

Date: 09/06/2021

Response: CA COMPLETED

Date of Completion: 08/31/2021

Operator  
Comment:

Briefly after receiving the FIR we visited location to verify organic compounds reported in pit. Based on the site pictures present in the FIR, it was suspected that high Iron Levels were responsible for the discoloration present. Samples were pulled at several locations by skimming the top of the pit to recover any hydrocarbons present in the pit. Lack of separation due to density along with the absence of any sheen was a strong indicator that hydrocarbons were not present (sample was let to sit for over 24 hrs.). A visual inspection of the location along with the pit resulted in the determination that hydrocarbons were not the cause of the pit discoloration, and that the most likely cause was high Iron content combined with coal fine discoloration and hardpan present in the natural soil from the pit. An Iron test taken in house using a mass spectrometer resulted in a reading of 4.80 mg/L which is significantly higher above the normal Iron content for the field. Sam Bollinger had a conversation with Jason Kosola in which they discussed the issue. They reached an agreement where all the information discussed was reproduced here in lieu of the hydrocarbon/organic compounds testing.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: THE CORRECTIVE ACTION HAS BEEN ADDRESSED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: Sr. Environmental Tech.

Date: 9/3/2021 9:08:30 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

--	--

Total Attach: 0 Files