

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/02/2021

Submitted Date:

09/03/2021

Document Number:

697601513

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: GINTAUTAS, PETER On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	<a href="#">All KPK Inspections</a>
Knop, Max	303-825-4822	MKnop@kpk.com	

**General Comment:**

Steel panel fencing in place surrounding excavation. No Operator staff present at time of inspection.

Ongoing Remediation project 19028 at now closed spill 479834.

Sorbent booms observed in main excavation in effort to minimize horizontal transport of crude oil in precipitation event are not in place near hydrocarbon liquids at time of inspection.

This inspection entered to document conditions observed at time of inspection. Operator has indicated they will remove observed hydrocarbon liquids and check on coninued seepage into excavation.

No barrier to prevent infiltration of crude oil and associated impacts to deeper soils and to shallow groundwater at site during precipitation or irrigation events.

**Environmental**

**Spills/Releases:**

Type of Spill: OIL Estimated Spill Volume: \_\_\_\_\_

Comment: attached photo to document presence of free hydrocarbon liquids/product floating on water at bottom of excavation for spill 479834. This is follow-up inspection to the FIR of 08/31/2021 and visible free hydrocarbon liquids present on that day appear to have been removed with more free liquids seeping into excavation from highly impacted soils seen at bottom of excavation

Corrective Action: remove free liquids/product within 24 hour of notice. Email notice sent on 09/2/21 and acknowledged by Operator staff on same day. email and response attached. Control and contain spills/releases and clean up per Rule 912.a.

Date: 09/03/2021

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601514	email notice and response 03Sept2021	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523965">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523965</a>
697601516	hydrocarbon liquids in excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523966">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523966</a>