

Inspection Photos
Operator: Kinder Morgan
API: 033-06185
Date: 10/11/2021



Photo 1. View of project area from the well pad entrance facing center. Well pad is reduced. Interim reclamation areas are revegetating.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with grasses in an early identifiable condition that appears to be intermediate wheatgrass, blue grama, western wheatgrass, as well as forbs such as showy goldeneye, penstemon, and purple asters.




Photo 3. View of the beginning of Transect 1, facing westward.



Photo 4. Birdseye view of revegetation along Transect 1, within the project area.



Photo 5. View of the beginning of Transect 2, within the reference area, facing northward.



Photo 6. Birdseye view of vegetation at midpoint along vegetation Transect 2, within the reverence area.



Photo 7. View of area along the access road where volumes of sediment are eroding down-slope. Additional stormwater and erosion control BMPs are needed here.



Photo 8. View of another area along the access road with evidence of sediment transport, and where existing BMPs are not adequate. Graded area adjacent to roadside ditch needs revegetation. Inset shows sediment discharge at bottom of slope.



Photo 9 View of reference area comprised of mixed pinyon/juniper, serviceberry and gambel oak shrubland. With understory of prickly pear, Indian ricegrass, rock goldenrod, and James galleta.