

Inspection Photos
Operator: Logos Operating
API: 067-05267
Date: 10/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Soils are not stabilized in this portion of the project area, with erosional channeling and sediment transport occurring. Inset shows an erosional channel approx. 12 in wide and deep in the southern fill slope.



Photo 3. View of the northern cut slope. Multiple erosional channels and sediment deposition occurring. Inset shows more erosional channeling and sediment deposition on the well pad.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with understory of sagebrush, James galleta, sandberg bluegrass, and prickly pear.