

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/05/2021

Submitted Date:

11/05/2021

Document Number:

700703485**FIELD INSPECTION FORM**

Loc ID 335639	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	----------------------------------	---	-------------------

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275672	WELL	PR	07/27/2005	GW	045-10369	CLOUGH RWF 433-10	PR
283610	WELL	PR	03/24/2006	GW	045-11970	CLOUGH RWF 333-10	PR
283611	WELL	PR	03/06/2006	GW	045-11971	CLOUGH RWF 33-10	PR
283612	WELL	PR	03/06/2006	GW	045-11972	CLOUGH RWF 533-10	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 11/4/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP RWF 433-10, at Location # 335639 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of tracking pad at time of inspection.

C/A (Erosion is occurring on cut slope that extends along south side of both levels of location. Riling, sediment migration, undermining of root systems, are resulting in general deterioration of slope) from previous inspection document # 692402767 has not been completed. During this inspection the following compliance issues were observed:

1. Load lines are missing bull plugs/caps
2. Quad unit horizontal separators includes 2 glycol storage tanks, storage vessels contain no labeling to specify capacity or chemical hazard information.
3. Location shows signs of lack of stabilization/compaction
4. Cut slope still shows signs of lack of stabilization/erosion from previous inspection (C/A date 4/15/2021)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	Quad unit horizontal separators includes 2 glycol storage tanks, storage vessels contain no labeling to specify capacity or chemical hazard information.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	CONTAINERS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Load lines are missing bull plugs/caps			
Corrective Action:	Comply with rule 603.i.			Date: 12/10/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	Chemical tanks in plastic containments			
Corrective Action:				Date:

Type: Bradenhead	# 4	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities									
Facility ID:	275672	Type:	WELL	API Number:	045-10369	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	283610	Type:	WELL	API Number:	045-11970	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	283611	Type:	WELL	API Number:	045-11971	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	283612	Type:	WELL	API Number:	045-11972	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				

Comment: 1. Location shows signs of lack of stabilization/compaction
 2. Erosion is occurring on cut slope that extends along south side of both levels of location. Riling, sediment migration, undermining of root systems, are resulting in general deterioration of slope (C/A date 4/15/2021)

Corrective Action: **Install or repair required BMPs**

Date: 04/15/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	422337	2213124	
	422337	2213124	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703500	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5573890