



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds unmanaged on location, Stained soil around pump jack motor and gear box, Stained soil around produced water tanks, stained soil under layout line to produced water tank.		
Corrective Action:	Comply with COGCC housekeeping rules.	Date:	06/15/2020
Type	OTHER		
Comment:	Inadequate berms around tank(s), and separator		
Corrective Action:	: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Inadequate berms around tank(s) Corrective action Date 6/15/2020,	Date:	06/15/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Unable to inspect due to weed growth on location		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	marked with steel fence post		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		

Comment:	
Corrective Action:	Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		
Comment: <span style="color:blue;">netting appears to be adequate at time of inspection</span>					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment: <span style="color:blue;">shares containment with oil tank</span>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment: <span style="color:blue;">Needs to be repaired.</span>				
Corrective Action:				Date:

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 202852 Type: WELL API Number: 001-08257 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

**Comment:** According to COGCC data this well has been shut in since 7/1/17. Missing production data from 8/1/19 to present. This well has been shut in for more than 2 years and is in need of a MIT according to MIT rules. Contact COGCC engineering.

**Corrective Action:** Comply with COGCC MIT rules for wells that have been shut in more than 2 years. Date: 11/11/2021

**BradenHead**

Date of Last Brhd Test: 12/31/2019 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: TSTM

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On 11/10/21 at approximately 1500 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Thompson-Price 2                      Company Name- Overland Resources LLC                      API- 05-001-08257                      In Adams County Colorado.                      While there, I observed SI well.                      This is a follow up inspection from document # 700900083 Corrective Actions are Delinquent                      During this inspection the following possible compliance issues were observed:                      Weeds unmanaged on location, Stained soil around pump jack motor and gear box, Stained soil around produced water tanks, staid soil under loaout line to produced water tank.                      Comply with COGCC housekeeping rules.6/15/20                      Inadequate berms around tank(s), and separator                      Repair or install berms or other secondary containment devices per Rule 605.a.(4).                      Inadequate berms around tank(s) Corrective action Date 6/15/2020,                      According to COGCC data this well has been shut in since 7/1/17. Missing production data from 8/1/19 to present. This well has been shut in for more than 2 years and is in need of a MIT according to MIT rules. Contact COGCC engineering.                      Comply with COGCC MIT rules for wells that have been shut in more than 2 years. 11/11/21                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	medinaj	11/11/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402869025	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579163">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579163</a>
699503342	Inspection Pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5579157</a>