

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2021

Submitted Date:

11/17/2021

Document Number:

697503506

**FIELD INSPECTION FORM**Loc ID 317861 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Whittington, Ellice		ellice.whittington@state.co.us	
,		cogcc@kpk.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240082	WELL	PR	08/01/2020	OW	123-07870	CARL R DEEPE B 1	RI

**General Comment:**

This inspection is in response to a reclamation complaint. Refer to the Location Lease Road, Complaint and Flowline sections for more details.

**Location****Lease Road:**

Type	Main		
comment:	COGCC Staff will be writing a corrective action to Oxy for failing to utilize the approved access road and failing to minimize surface disturbance per Rule 1002.e.(4). The corrective action will be asking Oxy to come to an agreement with KPK on which access road to utilize. If all parties agree to utilize the new Oxy access road, then Oxy shall reclaim the pre-existing access road illustrated in Photo #1. If all parties agree to utilize the pre-existing access road, then Oxy shall reclaim the new Oxy access road that was not approved.		
Corrective ActionL		Date:	
Type	Main		
comment:	After reviewing relevant files and historic aerial imagery, COGCC Staff believes KPK is utilizing a pre-existing access road prior to the new Kerr McGee (Oxy) Deep locations. Oxy planned and was approved to utilize the pre-existing access road illustrated in Photo #1. However, Oxy built a new access road that was not approved. Refer to the attached inspection photos.		
Corrective ActionL		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

## Inspected Facilities

Facility ID: 240082 Type: WELL API Number: 123-07870 Status: PR Insp. Status: RI

## Complaint

Comment: Complaint #: 402867524  
 Field Inspector Assigned: Chris Binschus  
 Location ID#: 317861  
 Inspection Document #: 697503506  
 Nature of complaint: Complainant indicated that KPK is utilizing an access road adjacent to a new flowline that was believed to be installed within the past year, instead of utilizing the new Oxy access road. Complainant has concerns about the subsidence along the flowline and vegetation.

Corrective Action:

Date:

## Flowline

#1	Type:	of Lines
----	-------	----------

## Flowline Description

Flowline Type: Size: Material:  
 Variance: Age: Contents:

## Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

## Pressure Testing

Witnessed: Test Result: Charted:

## COGCC Rules(check all that apply)

☒ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: There appears to be a flowline traveling north from well API# 123-07870 and ending near CR 20, which is connecting to the Facility 9 flowline system. It appears the well was in TA status for approximately 10 years and started producing August 2020. Operator has failed to submit a Flowline Report, Form 44, within 90 days after the flowline is placed in active status.

Corrective Action: Comply with Rule 1101.b.

Date: 11/16/2021

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.

#2	Type:	of Lines
----	-------	----------

## Flowline Description

Flowline Type: Size: Material:  
 Variance: Age: Contents:

## Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

## Pressure Testing

Witnessed: Test Result: Charted:

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

<u>Comment:</u>	Subsidence was observed throughout the majority of the flowline, which consists of annual, weedy vegetation.	
Corrective Action:	<p>Note- this is CRP land; therefore, Operator shall consult with the local NRCS on the appropriate seed mix. Operator shall make every reasonable effort to complete reclamation before the next local growing season.</p> <p>Comply with Rule 1102.f.(2) and 1102.f.(3).</p> <p>The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance.</p>	Date: <u>11/16/2021</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402873149	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583083">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583083</a>
697503507	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583082">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5583082</a>