

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2021

Submitted Date:

12/03/2021

Document Number:

696203395

FIELD INSPECTION FORMLoc ID 335950 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1001 17TH STREET #1900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335950	LOCATION	AC			-	CC 0697-16A2 Pad	RI

General Comment:

On 12/1/2021, Reclamation Specialist Trujillo inspected Laramie Energy's CC 0697-14A2 Pad location in Garfield County, Colorado.

This inspection is a followup to #696203158 and #696203346 to document compliance with the following corrective actions:
1002.f: Stormwater

Inspection is also a followup to Resolution #402877258 stating corrective action has been completed.

Refer to the "Stormwater" sections of this inspection report for additional details.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspection observed that stormwater and erosion control measures to manage runoff from the Location was inadequate; runoff resulted in gully erosion on the north end of the Location.

It was observed that Operator installed a sediment trap in conjunction with a slope drain and engineered outlet at the toe of the slope. Erosion degradation has been repaired.

Corrective action has been addressed; ensure stormwater and erosion control measures on the Location are maintained in proper functioning condition in accordance with good engineering practices.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696203396	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5595635