

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2022

Submitted Date:

01/14/2022

Document Number:

689501327**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Brown, Kari 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gorka, Ray		RGorka@kpk.com	KPK environmental
Rickard, Jeff		JRickard@kpk.com	KPK environmental
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481413	SPILL OR RELEASE	AC	01/13/2022		-	Firecracker Consolidation	EI

General Comment:

This is an environmental inspection of Spill ID 481413 (AC). Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

COGCC staff arrived on location 1/12/22 and observed an open excavation with orange construction present around the open excavation. Upon looking into the excavation area COGCC observed an active drip from the flowline at the spill source (photo 3). No crews were present at the excavation, however a KPK crew was present at a second excavation area north of the spill for flowline repair. COGCC staff discussed the drip with the KPK crew and it was determined at the cause was likely fluids pushed through while stinging the line. KPK crews addressed the drip and it was stopped by the time COGCC staff left the location.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type OTHER

Comment: Orange construction fencing present around open excavation (see photo 1).

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Excavation was open at the time of inspection and impacts remained visible in-situ (see photos 2&4).

Corrective Action: On the next supplemental Form 19 Operator is to provide the root cause of the incident and preventative measures that will be taken to prevent reoccurrence. Operator shall also give the location of the failure (i.e. 6 O'clock position) and if the root cause is corrosion explain if it is external or internal. In accordance with Rule 912.a.(6) No later than 90 days after a Spill or Release is discovered Operator will submit a Form 19 Supplemental requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate closure or a Form 27 Workplan with a timeline for investigation and closure of this release. If Remediation will continue under an approved Form 27, also submit a Form 19 ±Supplemental requesting closure of this spill referencing the approved Remediation workplan. Operator will provide notice to COGCC EPS Kari Brown (kari.l.brown@state.co.us) at least 48 hours prior to backfill or any sampling events preformed on location.

Date: 03/27/2022

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402927312	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5634034
689501328	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5634027