

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2022

Submitted Date:

06/02/2022

Document Number:

702800265**FIELD INSPECTION FORM**Loc ID 314277 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Olson, Andrew		AndrewOlson@chevron.com	Principle Agent Wilson Creek
Fischer, Alex		alex.fischer@state.co.us	
Puechner, Rachel		RPuechner@chevron.com	Decommissioning Advisor Wilson Creek
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
314277	LOCATION	AC			-	WILSON CREEK UNIT-63N94W 34NWNW	RI

General Comment:

On 05/25/2022, Reclamation Specialist O'Malley conducted a follow up inspection to #702800201 at Chevron USA Inc's Wilson Creek Unit-63N94W/34NWNW Location #314277 in Rio Blanco County, Colorado. West Environmental Supervisor, Alex Fischer was also present for the inspection.

The following compliance issues were observed during this inspection:

- Excavation lacks proper fencing
- BMPs to prevent E&P waste from migrating off Location missing or insufficient
- Stormwater: BMPs to manage stormwater missing or insufficient

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	<p>Previous inspection #702800201 observed that the area around the well has been excavated. Fence panels were present, but do not completely enclose the excavated area. Inspector required Operator to comply with Rule 913.b.(5).B.i by 5/15/22.</p> <p>It was observed in this inspection that fence panels were stored at the north of the Location and were not in use to enclose the excavation around the wellhead. Inspector acknowledges that at the time of this inspection a contractor was on Location preparing to continue work on the excavated area, therefore fence panels were temporarily decommissioned. Fencing should be reinstalled and continually maintained when work is not occurring. Original corrective action and date remain applicable.</p>		
Corrective Action:	Comply with Rule 913.b.(5).B.i.	Date:	05/15/2022

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspection #702800201 observed excavated soil stored on Location without BMPs to prevent E&P waste from migrating off Location. Inspector required Operator to Comply with Rule 913.b.(5).B.i-v by 5/15/22.

It was observed in this inspection that excavated soil was stored on Location. The Contractor on Location informed the Inspector that the Operator was waiting on delivery of wattles to address the previous corrective action. A berm of uncompacted soil was installed as a temporary control measure to prevent migration of E&P waste off site. Original corrective action and date remain applicable. Additionally, the berm may act as a sediment source/stormwater pollutant. No control measures were present to manage sediment runoff.

Corrective Action: Corrective Action #1: Comply with Rule 913.b.(5).B.i-v. CA Date: 5/15/2022

Date: 05/15/2022

Corrective Action #2: Install or repair required BMPs per Rule 1002.f. CA Date: 6/9/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702800266	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5768752