

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/06/2022

Submitted Date:

07/07/2022

Document Number:

699804665

FIELD INSPECTION FORM

Loc ID 316060 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 100 CHEVRON ROAD
City: RANGELY State: CO Zip: 81648

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Archuleta, Chris		carchuleta@chevron.com	Wilson Creek Field
dale, harber	970-824-8029	dhac@chevron.com	Wilson Creek
Ramsey, Scott		scott.ramsey@state.co.us	

General Comment:

[COGCC Inspection Report Summary](#)
On Tuesday 7/5/22 at approximately 12:00 hours, Inspector Scott Ramsey and I, Inspector Corey De Paolo, Conducted a follow up inspection at CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE. Location #316060 in Rio Blanco County Colorado. Refer to Document #699804662 inspection conducted on 6/30/22. While there, I observed multiple cranes and additional equipment that have been brought in to disassemble the damage Ranger workover rig. Both the rig tank and pump appear to not have been damaged by the fire. Additionally production equipment was not impacted by the fire. The workover rig tank and pump have been relocated. The flow back lines and hoses have been reconfigured. The rig pump has been moved further from the workover rig. It is now approximately 30 to 40 feet further to the North West of location. The pumps original location at the time of the fire was not compliant with COGCC rules. The workover rig tank has been moved from the North East corner of location to the South West side of the workover rig. The float trailer has been removed from location. Refer to photo log for equipment's original configuration and its current configuration. Chevron has maintained well control through the use of BOP blind rams. Refer to document #403094095 for form 22 and document #403094308 for from 19 submissions from Chevron. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	970-824-6452		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Fork lift		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig tank		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Excavator with shear		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig pump		
Corrective Action:		Date:	
Type: Other	# 1		

Comment: BOP and accumulator		Date:
Corrective Action:		Date:
Type: Other	# 1	
Comment: Workover rig		Date:
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment: Hydraulic cranes		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Berms						
Gravel						
Ditches						

Comment: Limited storm water inspection due to workover rig fire. At the time of inspection there did not appear to be any adverse impacts caused by the fire.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
	depaoloc	07/06/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804668	Photos for Insp. #699804665	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798478