

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2022

Submitted Date:

07/27/2022

Document Number:

694500447**FIELD INSPECTION FORM**Loc ID 458790 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10706Name of Operator: D90 ENERGY LLCAddress: 952 ECHO LANE SUITE 480City: HOUSTON State: TX Zip: 77024**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Joda, Ken	303-916-3854	ken@d90energy.com	

**General Comment:**

On 7/25/2022 COGCC staff, Kris Neidel inspected spill 482603 that was reported to COGCC by D90 (operator). The following was observed; a fine coat of oil had covered dirt outside of containment approximately 80 feet from the source of spill, some fluid (oil and water was pooling inside of the secondary containment). At the time of inspection, crews had removed some oil that had coated; piping, wiring, containment, pumps. D90 staff informed COGCC that all wells on pad were producing, either via triplex jet pump or rod pump. Vegetation that was impacted from the spray/spill should be removed and disposed of as E&P waste. The secondary containment should be evaluated for integrity, see photo #2 and #3. The adjacent triplex pump, on the Patriot 12-32, had what appeared to be excessive vibration in the piping off of pump, this vibration should be evaluated for proper operation. The Oxbow pad has 3 large generators and 6 conex that reportedly are mining bitcoin. It did not appear that the combustors were burning any gas.



**Environmental****Spills/Releases:**

Type of Spill: OIL \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: volume can not be estimated based on inspection. Spill was reported to COGCC.

Corrective Action: continue cleaning and document impacts compaired to Table 915-1.

Date: 08/02/2022

Reportable: YES \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: 250 \_\_\_\_\_

Depth to Ground Water: 30 \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403119411	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5814676">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5814676</a>
694500448	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5814675">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5814675</a>