

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/09/2022

Submitted Date:

09/13/2022

Document Number:

697601876

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Ahmadian, Alexander 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Cuthbertson, Scott		scott.cuthbertson@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
-, Marcom		primarycontractor@marcomllc.net	

General Comment:

Environmental inspection of Spill ID 482755 reported by Operator 8/13/2022 for the spill of oil, produced water, and condensate from the Rodgers #1 Flowline.

Environmental Inspections conducted 8/15/2022, 8/17/2022, 8/22/2022, 8/25/2022, 8/29/2022, 8/30/2022, 9/1/2022, and 9/6/2022.

At the time of inspection, crews were onsite and continuing remediation work on the spill excavations using two backhoes. Staining and high hydrocarbon odor were prevalent within the spill excavations.

A total of two excavations and one spill excavation was present at location; two excavations open for flowline repair and one consolidated spill excavation. Spill excavation size: 60'x32'x10'.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	<input type="text" value="Cattle panel fencing surrounds the orange construction fencing around all excavations."/>		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spill/Remediation:**

Comment: Remediation continued at the spill location. Crews were onsite using two backhoes to dig at the excavation. The two hydrovacted pothole excavations have been consolidated into one large excavation. Contaminated soil was emptied into a waste truck and hauled offsite. Obvious impacts remain visible in-situ. Hydrocarbon odors present outside of fencing.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
A Marcom representative was onsite collecting confirmation soil samples within the spill excavation. Base and east sidewall samples had visible staining, high odor, and high PID readings. North, south, and west sidewall samples had low PID readings.	ahmadiiaa	09/13/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601877	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5858236