

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2022

Submitted Date:

09/12/2022

Document Number:

690203374

**FIELD INSPECTION FORM**Loc ID 312051 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC		dnr_cogccenforcement@state.co.us	
, General		sjninspections@ikavenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263927	WELL	PR	02/15/2021	GW	067-08731	BARNES A 2	RI

**General Comment:**

This is a follow up of the previous reclamation inspection #693903865 and in regard to NOAV #403104776.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	There are numerous noxious weeds at the location such as Musk thistle, Houndstongue, Canada thistle that need to be controlled.		
Corrective Action:	Comply with Rule 1003.f.		Date: 09/23/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type:	#		
Comment:	Previous corrective action required submittal of Flood Shut In plan by 8/2/2021. NOAV #403104776 required submittal of plan on date of issuance, 7/13/2022. Operator did not submit the Flood Shut In plan until 8/16/2022.		
Corrective Action:			Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

**Comment:** Operator submitted the stormwater management plan on 8/3/2022, which was required per the NOAV #403104776 by 7/13/2022. Previous corrective action inspections required the plan to be submitted by 7/29/2021.  
It does not appear that stormwater management was fully implemented per the plan. There are areas along the eastern portion of the location described as "infiltration areas" which do not have perennial vegetation establishment. All interim reclamation areas of the location must be seeded and stabilized.

**Corrective Action:** COGCC accepts the submission of the stormwater plan however no approval will be provided since it is the Operator's responsibility to remain in compliance at all times regardless of a submitted plan. Stormwater management must be designed, implemented, and maintained according to good engineering practices which may require further actions beyond the scope of the plan.  
Install or repair required BMPs per Rule 1002.f.(2)C

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

**Comment:** COGCC considers open-top partially buried vessels (PBV) such as the PBV within the project area, as a pit. As such, these need to be constructed, maintained, and operated according to Rule 909. Specifically, the onsite PBV needs to be maintain with 2ft of freeboard per Rule 909.c

Corrective

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
1. The stormwater management plan does not indicate what storm event the plan is designed to accommodate.	CostaR	09/12/2022
2. The plan does not appear to address protection of all equipment in a high water situation which triggered the NOAV in first place, and should be part of the scope of planning for the location.		
3. The stormwater management plan may or may not be adequate for compliance of 900 series Rules during a high water situation to protect waters of the State.		

The open top tank has a steel grate which will not prevent spillage from occurring. Additionally the access door hatch should be kept secured due to instances where wildlife such as a bear can enter into tank. There has been known cases of wildlife mortality due to unsecured entry.

CostaR

09/12/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690203395	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5859769">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5859769</a>