

Inspection Photos

API: 071-09838

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 9/23/2022

Inspection Photos



Photo 1. The culvert outlet has eroded and needs to be repaired. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 9/23/2022

Inspection Photos



Photo 2. Facing toward the culvert outlet. The culvert outlet has eroded and needs to be repaired. Previous corrective action was not completed. BMP's must be installed per good engineering practice. (E.g. Rock outlet protection should include geotextile fabric)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 9/23/2022

Inspection Photos



Photo 3. The next culvert along the road is also eroded at the culvert outlet with no outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 9/23/2022

Inspection Photos



Photo 4. Facing southwest toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 9/23/2022

Inspection Photos



Photo 5. Facing southwest. There was rock rip/rap placed in this area where erosion had occurred. Stormwater is now going outside of the rip/rap area causing erosion at red arrow. Additional BMP's need to be installed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 9/23/2022

Inspection Photos



Photo 6. Facing east toward the location at the upper cut slope area. Stormwater run-on is causing erosion and is not properly diverted by the perimeter ditch. This area needs to be repaired and stabilized. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09838 | Date: 9/23/2022