

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2022

Submitted Date:

10/18/2022

Document Number:

696204259**FIELD INSPECTION FORM**Loc ID 335482 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335482	LOCATION	AC			-	Shell 0797-03B Pad	RI

General Comment:

On 10/17/2022, Reclamation Specialist Trujillo inspected Laramie Energy LLC's Shell 0797-03B location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

- Stormwater
- Storage of unused equipment, or equipment not needed for production
- Labeling
- Wildlife protection BMPs

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Tank with unknown contents observed stored behind separator equipment		
Corrective Action:	Provide proper labeling	Date:	11/02/2022

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused blower equipment stored on south end of Location		
Corrective Action:	Comply with Rule 606 and removed unused equipment, or equipment not necessary for production on the Location.		Date: 10/26/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type:	#		
Comment:	BMPs to prevent wildlife access to secondary containment adjacent to combustor unit missing or insufficient.		
Corrective Action:	Install or repair wildlife protection equipment.		Date: 10/28/2022

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
	Fail			Material Handling And Spill Prevention	Fail	

Comment: [See "COGCC Comments for Comments regarding Stormwater."](#)

Corrective Action: **Due to the nature of the erosion and degradation issues observed, the "date of inspection" is being provided as the CA date.**

Install or repair required BMPs per Rule 1002.f. Ensure BMPs are installed in accordance with good engineering requirements, and maintained in proper functioning condition.

Date: 10/17/2022

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>STORMWATER COMMENT</p> <p>Inspection #696202665 observed BMPs to stabilize and protect the cut slopes on the north end of the Location are missing, or insufficient. Inspection required Operator to comply with Rule 1002.f. Operator submitted FIRR #402690682 with documentation stating CA was completed.</p> <p>New observations per this inspection shows Operator failed to design, implement and maintain adequate stormwater controls in accordance with good engineering practices; BMPs to minimize erosion, degradation and sediment transport are missing or insufficient; extensive erosion degradation observed at the cut slopes of the Location resulting in substantial sediment deposition at the base of the slopes; there are areas where all fine soil material on the slopes have been lost. See photos 1-7.</p> <p>It was also observed that the stormwater discharge point on the southwest end of the Location has not been constructed with a properly engineered outlet; stormwater runoff has resulted in degradation at the outlet, with erosion progressing into the working pad area; runoff has eroded around and beneath the rip-rap armoring at outlet- gully erosion evident; outlet does not appear to have been constructed with a geotextile lining per good engineering requirements. See photos 8-11.</p> <p>It was also observed that spill prevention and/or containment BMPs are missing or insufficient at a tote-container on the west end of the Location. See photo 13.</p>	trujilloam	10/18/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204260	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5889932