

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/17/2022

Submitted Date:

10/25/2022

Document Number:

696204267

FIELD INSPECTION FORM

Loc ID: 335889
Inspector Name: Trujillo, Aaron
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections
,		dnr_cogccenforcement@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335889	LOCATION	AC			-	Cascade Creek 697-09-61	RI

General Comment:

On 10/17/2022, Reclamation Specialist Trujillo inspected Laramie Energy LLCs' Cascade Creek 697-09-61 Location in Garfield County, Colorado.

This inspection is a followup to:
[#696201787 dated 9/16/2020;](#)
[#696201980 dated 11/2/2020;](#)
[#696202122 dated 12/8/2020;](#)
[#696202928 dated 7/12/2021;](#)
[#696203107 dated 8/23/2021;](#)
[#696203152 dated 9/8/2021;](#)
 and [#696203338 dated 11/1/2021](#) to document compliance with the following corrective actions on the Location:

-1002.f: Stormwater

This inspection is also in response to NOAV #402812356 issued 9/15/2021.

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities

Facility ID: 335889 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See "COGCC Comments" for comment regarding Stormwater.](#)

Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C. Ensure control measures are adequate for the site's conditions, installed in accordance with good engineering practices, and maintained in proper functioning condition**

Date: 10/02/2020

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Pursuant to abatement or corrective action requirements per NOAV #402812356, Operator was required to provide a stamped, engineered stormwater plan showing designed short term and long term control measures to stabilize the slopes of the Location by 10/15/2021. It is noted that no stamped, engineered stormwater plan has been submitted, and the technical analysis provided within Operator's answer to the NOAV is not sufficient.	trujilloam	10/25/2022
STORMWATER COMMENT Previous inspections observed that BMPs to minimize erosion, degradation, as well as to stabilize and protect the cut slopes on the Location were missing or insufficient; Operator implemented erosion control blankets on the slopes of the north and west end of the Location; however, control measures to protect and stabilize a large section of cut slope remained missing or insufficient; previous inspections also observed that controls were not maintained in a proper functioning condition, that corrective actions requiring compliance with Rule 1002.f were not addressed, and remained applicable. It was observed in this inspection BMPs on the Location remain inadequate; control measures to minimize erosion, degradation, as well as to stabilize and protect the cut slopes remain missing or insufficient; erosion control blankets previously implemented remain in improper functioning condition- blankets largely in disrepair, and erosion degradation has resulted in sediment covering sections of remaining erosion control blankets. Control measures to protect and stabilize a large section of cut slope where erosion control blankets were not installed remain missing or insufficient, and erosion degradation has also persisted within these areas. Corrective actions have not been addressed and remain applicable.	trujilloam	10/25/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204268	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5895586