

# Inspection Photos

Loc: 333537

Operator: SIMCOE LLC / LOGOS OPERATING LLC

Inspection Date: 11/16/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022

## Inspection Photos



**Photo 1.** Facing northwest along the access road. There is vehicle rutting and erosion along the road that needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022

## Inspection Photos



**Photo 2.** Stormwater is not being directed toward the culvert at red arrow which is causing erosion of the road. Lat/Long:37.13286,-107.82855



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022

## Inspection Photos



**Photo 3.** Facing northwest along the access road. There is vehicle rutting and erosion along the road that needs to be repaired. Stormwater further up the drainage is being directed down the road to this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022

## Inspection Photos



**Photo 4.** Facing northwest along the access road. There is vehicle rutting and erosion along the road that needs to be repaired. Stormwater further up the drainage is being directed down the road to this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022

## Inspection Photos



11.16.2022

**Photo 5.** Stormwater from the drainage at right side of photo is being directed down the road and has washed out this culvert due to insufficient size of culvert. A larger or multiple culverts are need to allow proper drainage away from the road. Lat/Long:37.13507,-107.83293.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022

## Inspection Photos



**Photo 6.** Facing toward the Logos production equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022

## Inspection Photos



**Photo 7.** Facing toward the open top tank. Sediment has accumulated at the berm of the tank and stormwater is being directed into the tank. Stormwater needs to be diverted away from the open top tank and berm repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022

## Inspection Photos



**Photo 8.** Northwest side of the location facing southwest. The diversion ditch at red arrow has filled in with sediment causing stormwater and sediment to flow toward the open top tank.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022

## Inspection Photos



**Photo 9.** South side of the location facing east.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022

## Inspection Photos



**Photo 10.** Facing toward the wellsite. Simco sign is posted at the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc: 333537 | Date: 11/16/2022