

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2023

Submitted Date:

06/01/2023

Document Number:

702801561

FIELD INSPECTION FORM

Loc ID 335045	Inspector Name: O'Malley, Anna	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 25 Number of Comments 11 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Trujillo, Aaron		aaron.trujillo@state.co.us	
Arthur, Denise		denise.arthur@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	All Inspections
Gardner, Mike	9706234875	mgardner@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299205	WELL	SI	03/01/2023	GW	045-17609	SOUTH LEVERICH 13-10A	RI
299206	WELL	SI	03/01/2023	GW	045-17610	SOUTH LEVERICH 13-07B	RI
299207	WELL	SI	03/01/2023	GW	045-17611	SOUTH LEVERICH 13-09D	RI
301622	WELL	SI	03/01/2023	GW	045-18208	SOUTH LEVERICH 18-05D	RI
483796	WELL	AP	02/03/2023		045-24554	Leverich SR 322-13	RI
483797	WELL	AP	02/03/2023		045-24555	Leverich SR 321-24	RI
483798	WELL	AP	02/03/2023		045-24556	Leverich WMC 412-18-793	RI
483799	WELL	AP	02/03/2023		045-24557	Leverich WMC 523-18-793	RI
483800	WELL	AP	02/03/2023		045-24558	Leverich WMC 423-18-793	RI
483801	WELL	AP	02/03/2023		045-24559	Leverich WMC 514-18-793	RI
483802	WELL	AP	02/03/2023		045-24560	Leverich SR 523-13	RI
483803	WELL	AP	02/03/2023		045-24561	Leverich SR 423-13	RI
483804	WELL	AP	02/03/2023		045-24562	Leverich WMC 414-18-793	RI
483805	WELL	AP	02/03/2023		045-24563	Leverich SR 24-13	RI
483806	WELL	AP	02/03/2023		045-24564	Leverich SR 323-13	RI
483807	WELL	AP	02/03/2023		045-24565	Leverich SR 421-24	RI
483808	WELL	AP	02/03/2023		045-24566	Leverich SR 422-13	RI
483809	WELL	AP	02/03/2023		045-24567	Leverich SR 524-13	RI

483810	WELL	AP	02/03/2023		045-24568	Leverich SR 521-24	RI
483811	WELL	DG	05/25/2023		045-24569	Leverich SR 324-13	RI
483812	WELL	AP	02/03/2023		045-24570	Leverich WMC 512-18-793	RI
483813	WELL	AP	02/03/2023		045-24571	Leverich WMC 314-18-793	RI
483814	WELL	AP	02/03/2023		045-24572	Leverich SR 21-24	RI
483815	WELL	AP	02/03/2023		045-24573	Leverich SR 511-18	RI
483816	WELL	AP	02/03/2023		045-24574	Leverich SR 424-13	RI

General Comment:

On 5/30/2023, Reclamation Specialists O'Malley conducted a construction and stormwater inspection at TEP's South Leverich 13-09 Pad Location #335045 in Garfield County, Colorado.

This is a follow-up to inspection #702801487 to determine compliance with corrective actions relating to topsoil segregation and protection and stormwater management.

The following compliance issues were observed during this inspection:

- 1002.b: Topsoil segregation
- 1002.c: Topsoil protection
- 1002.e: Surface disturbance minimization
- 1002.f: Stormwater
- Noxious weeds

Refer to the "Location," "Construction," "Reclamation," "Stormwater" and "COGCC Comments" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been addressed.

LocationOverall Good: ☐**Signs/Marker:**

Type OTHER

Comment: Permit information per Rule 406.c observed at Location sign. Documents were previously saturated, frozen together and illegible. It appears new documents have been added to address the issue.

Corrective Action:

Date:

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: List B Noxious Weeds (Canada thistle, scentless chamomile) observed at the northwest of the location (Photo 33).

Corrective Action: Conduct weed management to prevent further establishment and spread of undesirable plant species and noxious weeds; ongoing weed management required until location passes final reclamation.

Date: 05/30/2023

Overall Good: ☐**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Location Construction

Location ID: 335045

CDP: _____

Comment: Form 2A permitted disturbance area during construction is 6.43 ac. It was observed in this inspection that it appears that disturbance has occurred in areas outside the permitted area. At the north of the location the construction drawing (#4223007) indicates that the location disturbance terminates at the perimeter stormwater BMPs (ditch and sediment trap). The actual location disturbance extends beyond the perimeter stormwater BMPs for approximately 70 feet to the north. To the east of the location entrance the location extends to the east of the access road. The construction drawing indicates that the location disturbance terminates west of the access road. See Photos 3, 28, 29, 30. COGCC is looking into this issue internally.

Corrective Action:

Date: _____

Form 2A COAs:

Comment:

Corrective Action:

Date:

Wildlife BMPs:**Comment:**

Corrective Action:

Date:

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
BERMS	Yes		

Comments: Erosion BMPs: It was observed in this inspection that the WPA perimeter berm is not constructed per good engineering practices; berm is loose, unconsolidated and vertical in portions (Photo 16).

Other BMPs: Run-on at the south of the location is breaking through the perimeter berm into the ditch and sediment trap. Accumulation of stormwater runon at the south, without a proper inlet appears to be causing degradation to BMPs (Photo 25, 26, 27).

Corrective Action: Install or repair BMPs per Rule 1002.f.

Date: 05/30/2023

WADDLES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: Previous inspection #702801487 observed straw wattles not trenched and backfilled around the topsoil stockpile. Inspector required Operator to Install or repair BMPs by 4/26/23. Operator submitted FIRR #403411071: "Wattles around the perimeter of the disturbed areas have been re-staked / installed."

It was observed in this inspection that wattles are installed at the topsoil stockpile per good engineering practice. However, a wattle is in disrepair (Photo 22). Original CA remains applicable.

Other BMPs:

Corrective Action: Install or repair BMPs per Rule 1002.f and 1002.c.

Date: 04/26/2023

DITCHES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: A diversion ditch is present along the Location perimeter. Construction of the ditch does not appear to be in accordance with good engineering practices; ditch soils are loose, unconsolidated and subject to erosion from concentrated flows in the ditch. BMP requires proper consolidation. (Photos 10, 11)

Other BMPs: Velocity checks have been installed within the perimeter ditch. (Photo 7, 10, 22, 27)

Corrective Action: Install or repair BMPs per Rule 1002.f.

Date: 05/30/2023

		Material Handling And Spill Prevention	No
--	--	--	----

Comments: Erosion BMPs:

Other BMPs:

Previous inspection #702801487 observed portable toilet on location not secured to prevent a spill. Inspector required Operator to Install or repair BMPs by 4/29/23. Operator submitted FIRR #403411071: "the trailer frame and attached toilette was secured with metal posts."

It was observed in this inspection that portable toilets on location are not secured to prevent a spill. No metal posts or other spill prevention BMP observed (Photo 32). Original CA remains applicable.

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention.

Date: 04/29/2023

Comments: Erosion BMPs:

Previous inspection #702801487 observed controls to stabilize the cut and fill slopes are missing/insufficient. Inspector required Operator to Install or repair BMPs by 4/27/23. Operator submitted FIRR #403411071: "Hydromulch has been re-applied to...slopes."

It was observed in this inspection that Hydromulch has been applied to slopes (Photo 19, 31). Corrective action has been addressed. However, new Hydromulch is degraded and slopes are unstable (slumping). Photo 17, 18, 20. New CA given.

Other BMPs:

Previous inspection #702801487 observed erosion control bags installed at the base of the fill slope and perimeter berm are in disrepair at the western perimeter of the location. Inspector required Operator to Install or repair BMPs by 4/27/23. Operator submitted FIRR #403411071: "Erosion control bags have been re-set around the perimeter."

It was observed in this inspection that erosion control bags are properly installed around the perimeter. Corrective action has been addressed (Photo 3).

Corrective Action: Install or repair BMPs per Rule 1002.f.

Date: 05/30/2023

Comments: Erosion BMPs:

It was observed in this inspection that two (2) slope drains are installed in the fill slope. Drains are not installed per good engineering practices; the pipe is not properly anchored, the pipe is discharging mid-slope/does not extend beyond the toe of the slope and lacks proper outlet protections (Photo 12).

Other BMPs:

Corrective Action: Install or repair BMPs per Rule 1002.f.

Date: 05/30/2023

Comments: Erosion BMPs:

Previous inspection #702801487 observed sediment traps at the west of the location appear to be designed to discharge stormwater directly into an unvegetated, unstabilized topsoil berm.

It was observed in this inspection that outlets, including to the west have been installed to discharge into vegetated, stabilized areas. Sediment trap inlets/outlets are installed with a geotextile liner and rip-rap (Photo 24). Operator shall monitor the site to ensure outlets do not cause offsite degradation.

Other BMPs:

Corrective Action:

Date:

Comments: Erosion BMPs:

Previous inspection #702801487 observed hydromulch on topsoil was not evenly distributed to cover the entire exposed soil surface. Operator submitted FIRR Resolution #403411071 indicating "Hydromulch has been re-applied."

It was observed in this inspection that hydromulch has been applied to the topsoil stockpile and is evenly applied over most of the stockpile. However, the hydromulch BMP is not fully maintained; a portion is degraded. A new corrective action is given. (Photo 21).

Other BMPs:

Corrective Action: Install or repair BMPs per Rule 1002.f and 1002.c.

Date: 05/30/2023

Comment:

Date:

Corrective
Action:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities				
Facility ID: <u>299205</u>	Type: <u>WELL</u>	API Number: <u>045-17609</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299206</u>	Type: <u>WELL</u>	API Number: <u>045-17610</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>299207</u>	Type: <u>WELL</u>	API Number: <u>045-17611</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>301622</u>	Type: <u>WELL</u>	API Number: <u>045-18208</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483796</u>	Type: <u>WELL</u>	API Number: <u>045-24554</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483797</u>	Type: <u>WELL</u>	API Number: <u>045-24555</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483798</u>	Type: <u>WELL</u>	API Number: <u>045-24556</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483799</u>	Type: <u>WELL</u>	API Number: <u>045-24557</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483800</u>	Type: <u>WELL</u>	API Number: <u>045-24558</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483801</u>	Type: <u>WELL</u>	API Number: <u>045-24559</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483802</u>	Type: <u>WELL</u>	API Number: <u>045-24560</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483803</u>	Type: <u>WELL</u>	API Number: <u>045-24561</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483804</u>	Type: <u>WELL</u>	API Number: <u>045-24562</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483805</u>	Type: <u>WELL</u>	API Number: <u>045-24563</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483806</u>	Type: <u>WELL</u>	API Number: <u>045-24564</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483807</u>	Type: <u>WELL</u>	API Number: <u>045-24565</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483808</u>	Type: <u>WELL</u>	API Number: <u>045-24566</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483809</u>	Type: <u>WELL</u>	API Number: <u>045-24567</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>
Facility ID: <u>483810</u>	Type: <u>WELL</u>	API Number: <u>045-24568</u>	Status: <u>AP</u>	Insp. Status: <u>RI</u>

Inspector Name: O'Malley, Anna

Facility ID:	483811	Type:	WELL	API Number:	045-24569	Status:	DG	Insp. Status:	RI
Facility ID:	483812	Type:	WELL	API Number:	045-24570	Status:	AP	Insp. Status:	RI
Facility ID:	483813	Type:	WELL	API Number:	045-24571	Status:	AP	Insp. Status:	RI
Facility ID:	483814	Type:	WELL	API Number:	045-24572	Status:	AP	Insp. Status:	RI
Facility ID:	483815	Type:	WELL	API Number:	045-24573	Status:	AP	Insp. Status:	RI
Facility ID:	483816	Type:	WELL	API Number:	045-24574	Status:	AP	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND, RECREATIONAL

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____ Fail _____

Comment [Refer to the "SOIL REMOVAL AND SEGREGATION" comments in the "COGCC Comments" section of this FIR.](#)Corrective Action [Corrective Action 1: Conduct additional topsoil salvage per Rule 1002.b: CA Date 4/25/2023.](#)Date **04/25/2023**[Corrective Action 2: Operator is being directed to propose an acceptable solution to the COGCC in order to resolve the soil salvage compliance issues. Operator shall provide meaningful solutions to address this issue. Submit in a Form 4 with a request that document is routed to Reclamation Specialist O'Malley. CA Date 6/6/2023.](#)

1002c. PROTECTION OF SOILS _____ Fail _____

Comment [Previous inspection observed topsoil has been applied to slopes... and Topsoil has been applied to slope directly adjacent to subsoil. Inspector required Operator to implement BMPs to protect topsoil applied throughout the location from erosion degradation and from contamination with subsoil by 4/27/23.](#)[It was observed in this inspection that topsoil applied to fill slopes has been hydromulched \(CA partially addressed\) but grub piles containing topsoil at the location perimeter continue to lack erosion protections \(Photo 4, 5, 6, 9\). Also, BMPs to protect topsoil from contamination with subsoil not observed \(Photo 14, 15\). Original CA remains applicable.](#)Corrective Action [Implement BMPs to protect topsoil applied throughout the location from erosion degradation and from contamination with subsoil.](#)Date **04/27/2023**

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment [Actual construction disturbance extends beyond permitted location disturbance area. Refer to the "Construction" section of this report.](#)

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: RANGELAND, RECREATIONAL _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:		
Corrective Action:		Date
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					WPA stable
Compaction	Pass					WPA stable
		Compaction	Pass			access road stable
		Ditches	Pass			access road stable
Other	Pass					Vehicle tracking not observed
		Gravel	Pass			access road stable

Comment: Previous inspection #702801487 observed location and access road lack stabilization. Also, a stormwater drain pipe was discharging concentrated flows without outlet protections. Operator submitted FIRR #403411071. See FIRR for details on corrective actions taken.

It was observed in this inspection that roads and the WPA are stabilized. The drain pipe to the east discharges into an armored outlet/sediment trap. Original corrective action has been addressed. However, walls of the newly installed sediment trap are unconsolidated. The trap outlet discharges water into a disturbed area of loose unconsolidated soil. Soils east of the access road required stabilization (Photo 28, 29).

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 05/30/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
-------	--------	---------	------	-------

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: Cuttings trench present at the south of the Location. Unable to find records that the cuttings trench has been permitted; no Form 15 permit observed within the Location records. A Form 15 is required to be submitted within 30 days of constructing the cuttings trench.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>SOIL REMOVAL AND SEGREGATION: Previous inspection #702801487 observed: 1. Topsoil not been salvaged from perimeter stormwater BMPs. 2. Discrepancies in the topsoil protection plan and COGCC disagreed with the depth of topsoil to be salvaged from the topsoil protection plan. Inspector required Operator to: 1. Conduct additional topsoil salvage per Rule 1002.b by 4/25/2023. 2. Submit documentation attached to a Form 4 of the actual amount of topsoil salvaged.</p> <p>It was observed in this inspection that: 1. Topsoil has not been salvaged from the areas where perimeter stormwater BMPs have been constructed. (Photo 7, 8, 10, 27, 28) Stormwater flowing through a BMPs constructed of topsoil may degrade and erode it. Standard engineering practice (ie: compaction, consolidation) for ditches and berms degrades the topsoil resource. Constructing stormwater BMPs (ditches and berms) from topsoil is not protective of the resource. Topsoil salvage at stormwater BMPs is required. Original corrective action remains applicable.</p> <p>2. TEP has submitted Form 4 #403411906 which included the requested topsoil calculations. Corrective action to submit Form 4 has been addressed. TEP indicates in the F4 that all the available topsoil was not salvaged and proposes to "address any long-term issues associated with site reclamation as they come." COGCC does not accept the plan for TEP to address issues with insufficient topsoil salvage in the future "as they come." TEP is being directed to propose meaningful, acceptable solutions to the COGCC to resolve the soil salvage compliance issues - not plans to address it if/when it arises during final reclamation.</p> <p>Refer to COGCC's analysis below of topsoil issues based on the amount of topsoil that was available pre-disturbance (in 2008) and will be available during final reclamation: - Total Disturbance area 2023: ~7.13 ac - Topsoil salvage area (total disturbance - topsoil area & grub piles): 6.432 ac - Topsoil salvage for 6.432 ac @ 12 in topsoil (12 in based on TEP topsoil protection plan undisturbed pits #4 and #11): 10,367 CY - Total topsoil salvaged per TEP as built assessment: 3,887 CY: A difference of 6,480 CY - 37.5% of originally available topsoil - Reclaiming the 6.432 ac disturbance with 3,887 CY of available topsoil results in 4.49 in of topsoil applied during final reclamation.</p> <p>CORRECTIVE ACTION DATE COMMENTS: The date of discovery is given for all new corrective action dates. It is COGCC's expectation that Operators are in compliance with COGCC rules at all times. Therefore, the date the location was observed out of compliance is given as the corrective action date. Location will remain out of compliance until corrective actions are addressed.</p>	omalleya	05/31/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403421278	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6133594
702801562	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6133169