

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2023

Submitted Date:

09/06/2023

Document Number:

708300856

FIELD INSPECTION FORMLoc ID 312601 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10770

Name of Operator: VISION ENERGY LLC

Address: P O BOX 370

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

10 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221999	WELL	SI	05/01/2010	CBM	077-08601	SOUTH SHALE RIDGE 4-13	SI

General Comment:**COGCC Inspection Report Summary**

On 9/6/2023 at approximately 09:50, Compliance Inspector Matthew Morris conducted a follow-up inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW at Location ID #312601 in Mesa County, Colorado.

Corrective actions from FIR #708300571 have not been completed and remain in effect.

During the inspection, the following compliance issues were observed:

- 1) Debris present across entire production area
- 2) Storage of supplies and equipment/unused equipment on location
- 3) Weeds present across entire production area
- 4) Signs; inaccurate signs at tank battery and wellhead/tank label missing tank capacity
- 5) Wildlife entry hazard on unused tank and vertical separator
- 6) Earth berm permeability inadequate due to weed growth
- 7) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Inaccurate operator information on battery sign.		
Corrective Action:	Install sign with current operator information to comply with Rule 605.e.	Date:	05/18/2023
Type	TANK LABELS/PLACARDS		
Comment:	Tank label missing volume capacity.		
Corrective Action:	Install label with tank capacity information to comply with Rule 605.h.	Date:	05/18/2023
Type	WELLHEAD		
Comment:	Sign not posted at wellhead.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/18/2023

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Vertical separator and unused fiberglass storage tank are damaged and pose a wildlife entry hazard.		
Corrective Action:	Install wildlife protection equipment on separator and tank to comply with Rule 608.a.	Date:	04/23/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location includes pump jacks, separator, fiberglass tanks, and other miscellaneous equipment.		
Corrective Action:	Remove unused equipment from location to comply with Rule 606.	Date:	05/18/2023
Type	WEEDS		
Comment:	Weeds and undesirable plant species present across entire location.		
Corrective Action:	Remove weeds and undesirable plant species from location to comply with Rule 606.	Date:	04/25/2023
Type	STORAGE OF SUPL		
Comment:	Storage of supplies and equipment on location.		
Corrective Action:	Remove stored supplies and equipment from location to comply with Rule 606.	Date:	04/25/2023
Type	DEBRIS		
Comment:	Debris present across entire location.		
Corrective Action:	Remove debris from location to comply with Rule 606.	Date:	04/25/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Separator	# 1		corrective date
--------------------------	-----	--	-----------------

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	Capacity not posted	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	Berm permeability is inadequate due to weed growth in berm.				
Corrective Action:	Repair earth berm to comply with Rule 603.o.				Date: 05/18/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	221999	Type:	WELL	API Number:	077-08601	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Last produced April 2010. Last MIT performed April 2022.</div>									
Corrective Action: <div></div> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Other	Fail			Insufficient vehicle tracking BMPs
Other	Fail					Insufficient vehicle tracking BMPs
Compaction	Fail					Location lacks stabilization
		Gravel				
Gravel						
		Ditches	Fail			BMP needs maintenance
Waddles	Fail					BMP degraded and insufficient
		Compaction	Fail			Rill erosion cutting through access road

Comment:

- 1) No BMP in place to prevent sediment run-on to location
- 2) Inadequate BMPs in place to minimize sediment transport from location
- 3) Inadequate vehicle tracking BMPs in place to minimize sediment transportation
- 4) Rill erosion cutting through lease road
- 5) No BMPs in place to minimize sediment transport in lease road ditch

Corrective Action:

Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 05/03/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403522241	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6243346
708300857	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6243343