

OCCIDENTAL PETROLEUM CORPORATION

Please contact your area engineer with any questions concerning this procedure.

1/17/2024

PLUG and ABANDONMENT PROCEDURE

PARKER 13-15A

API: 05-123-19841

WINS: 74443



Step Description

1	Review Previous Open Wells Reports/Well History. If you have questions or concerns, contact Foreman/Engineer.
2	COA: Provide 48 hour notice to Colorado ECMC prior to rig up per request on approved Form 6 (e.g. call field coordinator, submit Form 42, etc.).
3	Notify Automation Removal Group at least 24 hours prior to rig move. Request they catch and remove plunger, isolate production equipment, and remove any automation prior to rig MIRU.
4	MIRU Slickline. Pull production equipment and tag bottom. Record tag depth, casing/tubing pressures and fluid level in Open Wells. Gyro was run on 10/15/13. RDMO Slickline.
5	Prepare location for base beam equipped rig. Install perimeter fence as needed.
6	COA: Verify Form 17 (State Bradenhead Test) has been run within 60 days of RU.
7	Refer to the Rockies Well Services Guidelines document whenever rigging up BOP and WL, or whenever tripping in or out of the well. Consult with Foreman/Engineer before deviating from these guidelines.
8	Upon RU, check and record bradenhead pressure. If bradenhead valve is not accessible, re-plumb so that valve is above GL. Blow down bradenhead and leave open during working hours. Re-check pressure each day and input value in the "Casing press." box in Open Wells.
9	MIRU & CIBP
10	MIRU WO rig. Verify BOP and wellhead rating, inspect for appropriate API standards, pressure test BOP. Kill well as necessary using biocide treated fresh water. ND WH. NU BOP. Unland tbg. **Barrier Management** Fluid will be the only barrier while NU BOP. Stop and review JSA.
11	TOOH and SB 7362' of 2-3/8" tbg. LD remaining 2-3/8" tbg.
12	MIRU WL. PU and RIH with (4-1/2", 11.6#) gauge ring to 8010'. POOH.
13	PU and RIH with (4-1/2", 11.6#) CIBP and set at +/- 8000' . POOH. RIH and dump 2 sx cement on CIBP. POOH.
14	NIO INJECTION SQUEEZE
15	PU and RIH with one 4', 3-1/8" deep penetrating perf gun wth 4 spf. Shoot squeeze holes at 7392'. POOH. RDMO WL.
16	PU and TIH with (4-1/2", 11.6#) CICR on 2-3/8" tbg. Set CICR at 7362'.
17	MIRU cementers. Make sure the tubing annulus is loaded with water then attempt to establish injection max pressure 6150 psi with water. If it won't inject then sting out, load tubing with cement a bbl short of EOT then sting back in, in the next step. Max pressure is 3300 psi with tubing full of cement unless pressure is applied to annulus.
18	Pump Niobrara Injection Squeeze: 100 sx (27.1 bbl or 152 cf) of the Niobrara Cement blend: Class G with 0.4% B547 Gas Block (Latex) and 0.4% D255 FLA (Fluid Loss) and 35% D066 Silica Flour and 0.2% D800 (Retardant) and 0.3% D065 (Dispersant). Underdisplace by 1 bbls. Volume is based on 30' in the casing below the CICR, cement squeezed into formation, and 62' on top of the CICR. Collect wet and dry samples of cement to be left on rig. RDMO cementers.
19	Pull out of cement and reverse clean with 2x bottoms up. TOOH, SB 4460' of 2-3/8" tbg. LD remaining tbg.
20	SUSSEX INJECTION SQUEEZE
21	MI WL and run a CBL from 7200' to surface. Make sure to keep the hole full throughout the job, top off at the shoe, the uperrmost part of the log will be the most important part.
22	PU and RIH with one 4', 3-1/8" deep penetrating perf gun wth 4 spf. Shoot squeeze holes at 4490'. POOH. RDMO WL.
23	PU and TIH with (4-1/2", 11.6#) CICR on 2-3/8" tbg. Set CICR at 4460'.
24	MIRU cementers. Make sure annulus is full of water then attempt to establish injection with water, max pressure is 4150 psi , pipe is light at max. If it won't inject then sting out and load tubing with cement a bbl short of EOT then sting back in, in the next step. Max pressure is 3650 psi ,with tubing full of cement, pipe is light at max.

25	Pump Sussex Squeeze: 100 sx (21.2 bbl or 119 cf) of the Sussex AGM: Class G with 0.4% B547 Gas Block (Latex) and 2% D053 Expansion (Gyp) and 0.25% D255 FLA (Fluid Loss) 0.3% D065 (Dispersant). Underdisplace by 1 bbls. Volume is based on 30' in the casing below the CICR, cement squeezed into formation, and 60' on top of the CICR. Collect wet and dry samples of cement to be left on rig. RDMO Cementers.
26	Move up above cement top and reverse circulate 2X Bottoms up. TOO H and SB 1510' of 2-3/8" tbg. LD stinger, and remaining tbg.
27	UPPER PIERRE ROLL-OVER
28	MIRU WL. PU and RIH with two 4', 3-1/8" perf guns with 4 spf. Shoot 16 squeeze holes at 2200' and 16 squeeze holes at 1450'. RDMO WL.
29	PU and TIH with (4-1/2", 11.6#) packer on 2-3/8" tbg. Set packer at 1510'.
30	Initiate circulation at low rate monitoring returns for fluid. Add mud thinner to hydrate/clean mud. Slowly increase circulation rate to 4-6 BPM using mud thinner and gel polymer sweeps as needed.
31	Pump 54 bbls of 160F HSF (0.5 gals/bbl or 1.5 lbs/bbl) and let soak for ~2 hours.
32	Continue circulating at 4-6 BPM if possible. If returns show hydrocarbons or a 1 hr build-up shows pressure, swab and vent well and clean open tank. Circulate clean fluid before pumping cement.
33	Release packer. TOO H, SB 2-3/8" tbg. LD packer.
34	PU and TIH with (4-1/2", 11.6#) CICR on 2-3/8" tbg. Set CICR at 1510'.
35	MIRU cementers. Pump 10 bbls (min) of pre-flush, followed by 5 bbls fresh water spacer. Pump Squeeze: 250 sx (53.9 bbl or 303 cf) of the Lower AGM blend: Class G with 0.4% B547 Gas Block (Latex) and 1% S001 CC (Calcium Chloride) and 4% D053 Expansion (Gyp). Underdisplace by 5 bbls. Volume is based on 690' in the casing below the CICR, 750' in the casing-hole annulus with 25% excess, and 320' on top of the CICR. Collect wet and dry samples of cement to be left on rig. RDMO Cementers.
36	Pull out of cement. TOO H to 1090'. Reverse clean with 2x bottoms up.
37	TOO H and SB 840' of 2-3/8" tbg. LD stinger, and remaining tbg.
38	930' INJECTION SQUEEZE
39	MIRU WL. PU and RIH with one 4', 3-1/8" deep penetrating perf gun with 4 spf. Shoot squeeze holes at 930'. POO H. RDMO WL.
40	Pump down casing with water to break down perfs. Once the pressure breaks over check to see that you can get sufficient injection rate at 750 psi then stop pumping. Minimize volume pumped to prevent charging up the formation.
41	If gas is present, consider swabbing and venting before pumping injection squeeze.
42	PU and TIH with (4-1/2", 11.6#) CICR on 2-3/8" tbg. Set CICR at 900'.
43	MIRU cementers. Pump Squeeze: 100 sx of the Surface AGM blend: Class G with 0.4% B547 Gas Block (Latex) and 1% S001 CC (Calcium Chloride) and 4% D053 Expansion (Gyp). Underdisplace by 5 bbls. Volume is based on 690' in the casing below the CICR, cement squeezed into formation, and 320' on top of the CICR. Collect wet and dry samples of cement to be left on rig. RDMO Cementers.
44	Pull out of cement. TOO H to 800'. Reverse circulate 2x bottoms up.
45	TOO H and SB 840' of 2-3/8" tbg. LD stinger, and remaining tbg.
46	COA: WOC 8 hours. If there is evidence of pressure or fluid migration, contact Engineering as there will need to be additional remediation attempts before the SC shoe plug.
47	SHOE/SURFACE PLUG
48	COA: WOC 8 hours. If there is evidence of pressure or fluid migration, contact Engineering as there will need to be additional remediation attempts before the SC shoe plug.
49	TIH with 2-3/8" tubing to 840'. Establish circulation to surface with biocide treated fresh water and circulate bottoms up at 4-6 BPM.
50	Pump 14 bbls of 160F HSF (0.125 gals/bbl or 0.5 lbs/bbl) and let soak for ~1 hour.
51	COA: Verify and document that all pressure and fluid migration has been eliminated prior to placing the SC shoe plug at 840'. If there is evidence of pressure or fluid migration, contact Engineering.

52	MIRU cementers. Pump Surface Casing Shoe Plug: Pump 65 sx (14.1 bbl or 79 cf) of the Upper AGM blend: Class G with 0.4% B547 Gas Block (Latex) and 1.5% S001 CC (Calcium Chloride) and 4% D053 Expansion (Gyp). Volume is based on 840' in 4-1/2", 11.6# production casing with no excess. The plug is designed to cover 840'-0'. Plug length exceeds 500'. Consult with Foreman or Engineer on splitting up the plug. Verify and document cement to surface. Collect wet and dry samples of cement to be left on rig.
53	COA: If cement was not circulated to surface, then WOC 4 hours. Tag TOC. TOC must be 25' or shallower. If tag is too deep or there is evidence of pressure or fluid migration, contact Engineering.
54	TOOH insert ~5' of 2-3/8" Tbg. Circulate FW to clean Csg & Csg Valves. LD final joint of 2-3/8" Tbg. RDMO cementers. ND BOP. Install night cap. RDMO WO rig.
55	Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries to DJVendors@oxy.com within 24 hours of completion of the job.
56	Supervisor submit paper copies of all invoices, logs, and reports to Well Services Engineering Specialist.
57	Excavation crew to notify One Call to clear excavation area around wellhead and for flow lines.
58	Excavate hole around surface casing enough to allow welder to cut casing a minimum 5' below ground level.
59	Welder cut casing minimum 5' below ground level.
60	Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
61	Obtain marker plate GPS location data and provide to GPS Teams page and Oxy GIS database.
62	If applicable, abandon flow lines per Rule 1105. File electronic Form 42 and/or Form 44 once abandonment is complete.
63	Back fill hole with fill. Clean location, and level.
64	Submit Form 6 Subsequent Report to CECMC ensuring to provide 'As performed' WBD identifying operations completed.

Deepest WW 1 mile: Not Found'; FHM: 1167'; Sussex Top: 4476'; Sussex Base: 4701'; Shannon Base: 5140'; Niobrara Top: 7332'
WELL HAS GYRO. Gyro was run on 10/15/13.
No known casing integrity issues.
SUSSEX/SHANNON PRODUCTIVE WITHIN 1 MILE
Well was drilled by .
Vertical Well.