

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403734197

Date Received:

03/28/2024

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

1 of 6 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Katz, Aaron

aaron.katz@state.co.us

Engineering

dnr\_cogccengineering@state.co.us

TEP

COGCCInspectionReports@terraep.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708903238

Inspection Date: 03/07/2024

FIR Submit Date: 03/09/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 335556

Location Name: GYPSUM RANCH-66S93W Number: 14SWNW County: \_\_\_\_\_

Qtrqtr: SWN Sec: 14 Twp: 6S Range: 93W Meridian: 6

W

Latitude: 39.526851 Longitude: -107.751955

### FACILITY - API Number: 05-045- -00 Facility ID: 335556

Facility Name: GYPSUM RANCH-66S93W Number: 14SWNW

Qtrqtr: SWN Sec: 14 Twp: 6S Range: 93W Meridian: 6

W

Latitude: 39.526851 Longitude: -107.751955

### CORRECTIVE ACTIONS:

5 ☒ CA# 192905

Corrective Action: Contact CECMC Engineering group & discuss observed compliance issue

Date: 03/16/2024

Response: CA COMPLETED

Date of Completion: 03/13/2024

TEP discussed this Corrective Action with EECMC's Aaron Katz on March 13, 2024. TEP informed Aaron that the bradenhead was plumbed to the ECD by the former Operator of the well and that TEP has never utilized the

Operator Comment: bradenhead connection to the ECD to manage bradenhead pressure. TEP has confirmed that the valve on the piping to the ECD is closed and this valve was also closed at the time of the ECMC inspection based on our review of the inspection photos. TEP informed Aaron that the bradenhead pressure is currently zero psi and that the piping from the bradenhead to ECD will be disconnected as soon as possible.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Action #192905 has been completed.

TEP discussed this Corrective Action with ECMC's Aaron Katz on March 13, 2024. TEP informed Aaron that the bradenhead was plumbed to the ECD by the former Operator of the well and that TEP has never utilized the bradenhead connection to the ECD to manage bradenhead pressure. TEP has confirmed that the valve on the piping to the ECD is closed and this valve was also closed at the time of the ECMC inspection based on our review of the inspection photos. TEP informed Aaron that the bradenhead pressure is currently zero psi and that the piping from the bradenhead to ECD will be disconnected as soon as possible.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 3/28/2024 8:23:48 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

|           |                          |
|-----------|--------------------------|
| 403734197 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files