

# Interim Reclamation and Stormwater Inspection

Date: 06/13/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 312291

Inspection Document #: 708201332

Logan County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 1.** Areas experiencing erosion degradation throughout the production areas do not appear to have been repaired/stabilized and there is no evidence of stormwater controls measures/BMPs having been implemented.





**Photo 2.** Taken from the access road east of the pit. Evidence of erosion degradation, previously documented, does not appear to have been repaired/stabilized with no evidence of control measures/BMPs observed that would prevent further erosion of the access road.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 3.** Taken from the access road, facing northeast; see comments in Photo 2.





**Photo 4.** Continued from Photo 3. Sediment deposition pictured.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 5.** Taken from the access road, facing northwest; see comments in Photo 2.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 6.** Taken from the access road, facing northwest; see comments in Photo 2.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



6/13/24, 1:47 PM  
310° NW  
ECMC

**Photo 7.** Taken from the access road, facing northwest; see comments in Photo 2. Subsidence pictured.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 8.** Taken from the production area, facing southeast along the access road; see comments in Photo 2.





**Photo 9.** Erosion degradation occurring along the production areas; see comments in Photo 2.





**Photo 10.** Erosion degradation occurring along the production areas; see comments in Photo 2.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 11.** No wildlife netting covering the pit was observed during this inspection.






**Photo 12.** Free fluids observed within secondary containment have not been properly disposed of.





**Photo 13.** Taken from the north side of the stockpiled soils. No perimeter stormwater control measures/BMPs, or impermeable liners underneath the stockpile were observed during this inspection. Impacted soils appear to have been placed directly on top of undisturbed lands. Additionally, it does not appear that topsoil has been salvaged Per Rule 1002.b prior to stockpiling the soil on undisturbed portions of land.





**Photo 14.** Riling observed on the stockpiled materials; see comments in Photo 13.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 15.** Taken southwest of the excavated area and stockpiled material; see comments in Photo 13.





**Photo 16.** Continued from Photo 15, facing southwest. Sediment deposition pictured.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 17.** Taken from the southern portion of the stockpiled material; see comments in Photo 13.





**Photo 18.** Taken from the southeast corner of the stockpiled material; see comments in Photo 13.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 19.** Taken southeast of the excavated area and stockpiled material; see comments in Photo 13.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 20.** Continued from Photo 19, facing west.





**Photo 21.** East side of pit; Stormwater control measures around the pit remain inadequate.



Inspection Photos  
Location Name: Propst 1  
Location ID: 312291



**Photo 22.** Continued from Photo 21.





**Photo 23.** Northeast corner of the pit; erosion degradation pictured. Stormwater control measures around the pit remain inadequate.





**Photo 24.** Northeast corner of the pit; erosion degradation pictured. Stormwater control measures around the production areas remain inadequate.