



**Step Description**

1	Well is being re-entered to P&A well to current standards due to it being offset to upcoming fracs.
2	<b>Provide 48 hour notice to Colorado ECMC prior to rig up per request on approved Form 6 (i.e. submit Form 42, etc.)</b>
3	Perform pre-job safety meeting and review JSA. Ensure all parties know their roles and responsibilities and can identify hazards.
4	Follow all Rockies Well Servicing guidelines.
5	Stop and complete new JSA prior to all barrier changes.
6	<b>Attempt to leave kill string in the hole every evening/weekend. If this is not possible, discuss with foreman/engineer.</b>
7	<b>Locate and expose 8-5/8" casing stub.</b>
8	Tie into and weld on 8-5/8" casing stub above GL.
9	Install 8-5/8" 3K Q92 well head with ball valves on both outlets.
10	Check and record surface casing pressure.
11	MIRU CT unit/crane/equipment/tanks/pumps.
12	Perform negative test and ensure well is dead. Wait 15-30 minutes to verify (cement is at surface).
13	Pressure test BOPE, annular and 2" 1509 iron to API standards. Chart and record pressure tests. Please refer to Testing Procedures and Testing Table listed in the APPENDIX tab. All tests are performed on stump. Note: ensure BOPE accumulator controls are properly placed and pressurized.
14	NU and torque BOPE to casing head. Communicate with engineer, foreman, CT rep on correct BOP.
15	Test TIW valves. Chart tests and document accordingly.
16	Confirm with engineer, foreman and CT rep with BHA design.
17	PU and TIH with 2-3/8" CT with drill bit and motor.
18	Drill 10 sx cement plug from surface through estimated BOC at 28'. Continue drilling out 20 sx cement plug at shoe, BOC estimated 186'. IF WE BEGIN TO SEE INDICATION OF NEW FORMATION BEING DRILLED, STOP AND DISCUSS W/ FOREMAN/ENGINEER. Wash down to 20 sx plug at 525' and drill through plug to 700'.  Continue drillout and wash down to 2500'. Contact engineering if plug is not tagged at depth.
19	Circulate with biocide treated fresh water to clean the hole. Pump until returns are clean.
20	Run gyro or use directional survey.
21	TOOH, LD drill bit and BHA.
22	PU and TIH with 8-5/8" bit and scraper. Clean surface casing from surface to 172'. Run scraper over 60' to 80' 2-3 times to ensure casing is clean for CIBP. TOOH, LD bit and scraper.
23	TIH to 2500'. Establish circulation to surface with biocide treated fresh water to clean up wellbore. Start at a low rate, and increase rate once returns are clean.
24	MIRU cements. Pump Open Hole Plug: Pump 285 sx (60.5 bbl or 340 cf) of the Sussex AGM: Class G with 0.4% B547 Gas Block (Latex) and 2% D053 Expansion (Gyp) and 0.25% D255 FLA (Fluid Loss) 0.3% D065 (Dispersant). Volume based on 500' in 7.875" bit size open hole with 100% excess factor. Cement will be from 2000'-2500'. Collect wet and dry samples of cement to be left on rig. RDMO Cements. Notify engineering if circulation is ever lost during job.
25	Pull out of cement. TOOH to 1800'. Forward circulate tbg clean. TOOH. WOC 4 hours.
26	<b>COA: Prior to pumping cement into the Upper Pierre, verify all fluid migration has been eliminated. Contact engineering if pressure remains.</b>
27	TIH to 1800'. Establish circulation to surface with biocide treated fresh water to clean up wellbore. Start at a low rate, and increase rate once returns are clean.

28	MIRU cementers. Pump Upper Pierre Plug: Pump 285 sx (61.5 bbl or 345 cf) of the Lower AGM blend: Class G with 0.4% B547 Gas Block (Latex) and 1% S001 CC (Calcium Chloride) and 4% D053 Expansion (Gyp). Volume based on 500' in 7.875" bit size open hole with 100% excess factor. Cement will be from 1300'-1800'. Collect wet and dry samples of cement to be left on rig. RDMO Cementers. Notify engineering if circulation is ever lost during job.
29	Pull out of cement. TOOH to 880'. Forward circulate tbg clean. TOOH.
30	<b>COA: WOC 8 hours. If there is evidence of pressure or fluid migration, contact Engineering as there will need to be additional remediation attempts before the SC shoe plug.</b>
31	TIH to 880'. Establish circulation to surface with biocide treated fresh water to clean up wellbore. Start at a low rate, and increase rate once returns are clean.
32	Load hole with 50 bbls of heated surfactant to clean surface casing walls, wellhead, and surface valves/lines. Let soak for at least 2 hours. Circulate out heated surfactant with fresh water.
33	MIRU cementers. Pump 10 bbls (min) of pre-flush, followed by 5 bbls fresh water spacer. Pump Surface Casing Shoe Plug: Pump 280 sx (60.4 bbl or 339 cf) of the Upper AGM blend: Class G with 0.4% B547 Gas Block (Latex) and 1.5% S001 CC (Calcium Chloride) and 4% D053 Expansion (Gyp). Volume is based on 708' in 7.875" bit size open hole with 100% excess factor. 72' in the 8-5/8", 24# surface casing with no excess. The plug is designed to cover 880'-100'. Plug length exceeds 500'. Consult with Foreman or Engineer on splitting up the plug. Collect wet and dry samples of cement to be left on rig. RDMO Cementers. Notify engineering if circulation is ever lost during job.
34	Pull out of cement. TOOH to 80'. Reverse circulate tbg clean with fresh water. WOC.
35	<b>COA: If cement was not circulated to surface, then WOC 4 hours. Tag TOC. TOC must be 91' or shallower. If tag is too deep or there is evidence of pressure or fluid migration, contact Engineering.</b>
36	MIRU WL. RIH and tag cement with gauge ring to verify appropriate coverage above the surface casing shoe. Notify engineering if tag is low. Pressure test TOC to 500psi for 15 minutes. Record and notify engineering and foreman of results.
37	MIRU WL. PU and RIH with (8-5/8", 24#) CIBP and set at 80'. POOH. RDMO WL.
38	TIH with diverter tool on 2-3/8" tubing to 80'. Either swab well down or use rig air to remove water from well. (Note: Do not exceed 175 psi if using rig air). If either methods cannot be performed, contact engineering to discuss excess cement volume for top out plug.
39	DO NOT PUMP WATER AHEAD OF CEMENT. MIRU Cementers. Pump Surface Plug: Pump 25 sx (5.4 bbl or 31 cf) of the Surface AGM blend: Class G with 0.4% B547 Gas Block (Latex) and 2% S001 CC (Calcium Chloride) and 4% D053 Expansion (Gyp). Volume based on 80' inside 8-5/8", 24# surface casing with no excess. Cement will be from 80' to surface. Verify and document cement to surface. Collect wet and dry samples of cement to be left on rig.
40	Pull out of cement. Circulate clean with water to ensure TOC is low enough for C&C team. RDMO cementers. ND BOP. Install night cap. RDMO CT unit.
41	Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries to rscDJVendors@oxy.com within 24 hours of completion of the job.
42	Supervisor submit paper copies of all invoices, logs, and reports to Well Services Engineering Specialist.
43	Excavation crew to notify One Call to clear excavation area around wellhead and for flow lines.
44	Excavate hole around surface casing enough to allow welder to cut casing a minimum 5' below ground level.
45	Welder cut casing minimum 5' below ground level.
46	Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
47	Obtain GPS location data and provide to GPS Teams page and OXY GIS database.
48	Back fill hole with fill. Clean location, and level.
49	Submit Form 6 Subsequent Report to Colorado ECOMC ensuring to provide 'As performed' WBD identifying operations completed.
50	MIRU WL. PU and RIH with (8-5/8", 24#) CIBP and set at 90'. POOH. RDMO WL.
51	TIH with diverter tool on 2-3/8" tubing to 90'. Either swab well down or use rig air to remove water from well. (Note: Do not exceed 175 psi if using rig air). If either methods cannot be performed, contact engineering to discuss excess cement volume for top out plug.

52	DO NOT PUMP WATER AHEAD OF CEMENT. MIRU Cementers. Pump Surface Plug: Pump 30 sx (6.5 bbl or 37 cf) of the Surface AGM blend: Class G with 0.4% B547 Gas Block (Latex) and 2% S001 CC (Calcium Chloride) and 4% D053 Expansion (Gyp). Volume based on 90' inside 8-5/8", 24# surface casing with no excess. Cement will be from 90' to surface. Verify and document cement to surface. Collect wet and dry samples of cement to be left on rig.
53	TOOH and remove diverter tool. Insert ~5' of 2-3/8" Tbg. Circulate FW to clean Csg & Csg Valves. LD final joint of 2-3/8" Tbg. RDMO cementers. ND BOP. Install night cap. RDMO WO rig.
54	Instruct cementing, tools and wireline contractors to e-mail copies of all job logs/job summaries to rscDJVendors@oxy.com within 24 hours of completion of the job.
55	Supervisor submit paper copies of all invoices, logs, and reports to Well Services Engineering Specialist.
56	Excavation crew to notify One Call to clear excavation area around wellhead and for flow lines.
57	Excavate hole around surface casing enough to allow welder to cut casing a minimum 5' below ground level.
58	Welder cut casing minimum 5' below ground level.
59	Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
60	Obtain GPS location data as per Colorado ECMC Rule 215 and provide to GPS Teams page and Oxy GIS database.
61	Properly abandon flow lines per Rule 1105. File electronic Form 42 and/or Form 44 once abandonment is complete.
62	Back fill hole with fill. Clean location, and level.
63	Submit Form 6 Subsequent Report to Colorado ECMC ensuring to provide 'As performed' WBD identifying operations completed.